

(08/11/13) wef

ASS. REC. BY: Am

REF:

CS/AIS23002136/Rvg3

7212

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLW 8878Tat Workshop m/s CYCLE & CARRIAGEof 188, Pymon Loop

Insured:

ALWPolicy No. SP2004083122-01Claims No. 202332005717

Sum Insured:

Excess:

700

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

187K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLW 8878T

Yr Regn:

2021 JANType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ GLB 200 PRO c.c 1332

Colour

RED

A/C: Insured / Std / NI / NA

Sp. Reading

40401

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WIN2476872W068877Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/02/23

D.O.I.

01/03/23

Survey held at

CYCLE & CARRIAGE PL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 123K

16/3/23

Final fig \$7626.02 confirmed by email (Red 6781.66, 47%)

Date/Time, File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 20/3/23-typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : Merimen

Lump Sum / I.B.I: (\$ 7626.02



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW8878T

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 63241
Reg No/Reg Date SLW8878T / 15/01/2021
Date In/Mileage / 0
Chassis No W1N2476872W0688778
Engine No 28291480423362
Make/Model MB/GLB 200
Colour/Trim 029 993 Patagonia R/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator					
WA000001	Credit	27/02/2023/ 13:26	VS	356 / Vincent Seah					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE :SP2004083122-01 // 25.02.2023									
DRIVE IN/EXCESS :25.02.2023 //									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
M BPNSUN									15.00
SUNDRIES									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
A BPILAB									0.10
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT									380.00
A BPILAB									120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT									1440
A BPILAB									2880.00
PANEL BEAT TO REPAIR AFFECTED AREAS. REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.									800
A BPIRES									2400.00
RESPRAY ON LHF FENDER , FRONT BUMPER AND ACCIDENT AFFECTED AREA									
M LEFT HEADLAMP UNIT ?	1.00	3361.30	00.00		3361.30				
M CROSS MEMBER X	1.00	473.00	00.00		473.00				
M FRONT SUPPORT CONNECTING CARRIER ?	1.00	728.80	00.00		728.80				
M LEFT FENDER FRONT X	1.00	1479.57	00.00		1479.57				
M LHF EDGE GUARD ?	1.00	9.42	00.00		9.42				
M LHF FENDER MOULDING 354-	1.00	268.90	00.00		268.90				
M LHF FENDER OUTER LINEAR ?	1.00	195.71	00.00		195.71				
M LHF FENDER LOWER COVERING ?	1.00	63.46	00.00		63.46				
M BRACKET, LHF FENDER (FRONT) ?	1.00	60.47	00.00		60.47				
M FRONT BUMPER 500-	1.00	1240.82	00.00		1240.82				
M LHF UPP BASIC CARRIER FOR BUMPER ?	1.00	53.72	00.00		53.72				
M LHF TOP MOUNTING RAIL ?	1.00	71.06	00.00		71.06				

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6298 5222



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW8878T

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

WIP No 63241
Reg No/Reg Date SLW8878T / 15/01/2021
Date In/Mileage / 0
Chassis No W1N2476872W0688778
Engine No 28291480423362
Make/Model MB/GLB 200
Colour/Trim 029 993 Patagonia R/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	27/02/2023/ 13:26	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LH/E BUMPER BRACKET	1.00	49.07	00.00	49.07
M LHF BASIC CARRIER FOR BUMPER	1.00	66.97	00.00	66.97
M IMPACT ABSORBER	1.00	174.98	00.00	174.98
M LH/F FOGLAMP COVER	1.00	54.47	00.00	54.47
M FRONT BUMPER LOWER GRILLE	1.00	260.96	00.00	260.96

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

Nett 14,407.68
8% GST on 14407.68 1152.61
Total Payable 15,560.29

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 721Z

Vehicle Details

Vehicle No.: SLW8878T

Vehicle to be Exported: No

Intended Deregistration Date: 01 Mar 2023

Vehicle Make: MERCEDES BENZ

Vehicle Model: GLB200 PROGRESSIVE

Primary Colour: Red

Manufacturing Year: 2020

Engine No.: 2B291480423362

Chassis No.: W1N2476872W068877

Maximum Power Output: 120.0 kW (160 bhp)

Open Market Value: \$37,122.00

Original Registration Date: 15 Jan 2021

First Registration Date: 15 Jan 2021

Transfer Count: 0

Actual ARF Paid: \$43,971.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jan 2031

PARF Rebate Amount: \$32,978.00

Intended COE Rebate Details

COE Expiry Date: 14 Jan 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$39,000.00

COE Rebate Amount: \$30,686.00

Total Rebate Amount: \$63,664.00

Mercedes-Benz GLB-Class GLB200 Progressive

Overview Financial Accessories Similar Research Photos Map

Price	\$187,688		
Depreciation 	\$21,110 /yr View models with similar depre	Reg Date	07-Jan-2021 (7yrs 10mths 8days COE left)
Mileage	29,000 km (13.5k /yr)	Manufactured 	2020
Road Tax 	\$586 /yr	Transmission	Auto
Dereg Value 	\$63,353 as of today (change)	OMV 	\$36,865
COE 	\$39,000	ARF 	\$43,611
Engine Cap	1,332 cc	Power	120.0 kW (160 bhp)
Curb Weight 	1,555 kg	No. of Owners 	1
Type of Vehicle	SUV		