

FRONT & REAR

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4868L

DATE 23.11.2022

MAKE REG 30.05.2017

MODEL PRIUS G4

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			de \$586.18
1	FRT BUMPER REINFORCEMENT			bt \$812.89
1	FRT BUMPER REINFORCEMENT ABSORBER LH /RH		\$115.70	X \$231.40
1	FRTBUMPER CENTRE GRILLE			de \$166.90
1	FRT BUMPER LOWER GRILLE			de \$301.90
1	FRT BUMPER TOW COVER			de \$28.38
10	BUMPER CLIPS		\$2.20	new \$22.00
1	FRONT NUMBER PLATE EXTENSION			new \$99.00
1	BONNET			bt \$1,117.93
2	BONNET HINGE LH/RH		\$87.70	8 \$175.40
1	FRT GRILLE EMBLEM			new \$88.00
2	HEAD LAMP LH/ RH		\$2,637.60	\$5,275.20
2	FRONT DAYLIGHT LH/ RH		RH X \$642.00	\$1,284.00
2	FRT BUMPER SIDE RETAINER /RH		\$77.00	\$154.00
1	FRONT SUPPORT RAD TOP			\$361.10
1	FRONT SUPPORT LOWER			\$267.43
2	FRONT RAD SUPPORT LH/RH		\$278.68	\$278.68
1	AC CONDENSER ASSY			\$1,336.60
1	RADIATOR ASSY			\$1,841.80
1	RADIATOR FAN COWLING			\$451.30
2	RADIATOR FAN MOTOR LH/RH		\$543.70	\$1,087.40
2	RADIATOR FAN LH/RH		\$233.10	\$466.20
1	RADIATOR SPARE TANK			\$126.50
SUB TOTAL				\$16,560.19
LESS 25%				\$4,140.04
DISCOUNTED TOTAL				\$12,420.14
2	FRONT FENDER ADVERTISEMENT		\$100.00	\$200.00
1	FRONT NUMBER PLATE W/HOLDER			\$55.00
Labour Charge				\$255.00
Panel Beating				
Spray Painting Charge				
Check Wiring & Lighting				
Towing Fee				
Charge in Air Con Gas				
TOTAL LABOUR				\$1,990.00
ESTIMATE TOTAL				\$14,665.14

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9749594 9
 Wp 25/11/22 24pm
 4/3 Resurvey after repair
 Tanpin Cllhamp.com 03 days

1580

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4868L

DATE 23.11.2022

MAKE REG 30.05.2017

CHIANG/ICHINA

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			all \$503.04 /
1	REAR BUMPER LOWER COVER			all \$654.96 /
1	REAR BUMPER REINFORCEMENT			? \$378.32 /
1	REAR BUMPER RH LOWER COVER			all \$232.00 /
2	REAR BUMPER SIDE RETAINER LH/ RH		L4X \$112.70	R4de \$225.00
10	REAR BUMPER CLIP		\$2.20	nei \$22.00 /
	SUB TOTAL		15 24.70	\$2,015.32
	25.00%		1143.52	\$503.83
	DISCOUNTED TOTAL			\$1,511.49
1	REAR BUMPER MAT			nei \$50.00 /
1	REAR BUMPER ADVERTISEMENT			out \$50.00 /
1	BUMPER REVERSE SENSOR			185.70 \$135.70 /
				\$222.13
	Labour Charge			
	Panel Beating		250	\$550.00
	Spray Painting Charge		250	\$300.00
	Tuff Kote		nm. x	\$60.00
	Remove/Refix Reverse Sensor		30	\$60.00
	TOTAL LABOUR		630	\$970.00
	ESTIMATE TOTAL			\$2,703.62

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphui 92495745
 - WP' 25/11/22 e Y/m
 02 days
 H/s Kuning after repair
 Tanphui e lkhauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORT DELGRO ENGINEERING

VEHICLE I SHA4868L

CHINA

305537657

TYPE OF C: TP

SURVEY B': LKK/TAUFIKH

DATE : 23.11.2022

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE	\$	REMARKS
FENDER EMBLEM	1		86.60	rec ✓
FEHDER LH	1		1111.93	ht ✓
BONNET LOCK	1		132.60	ht ✓
INLET AIR CLEANER N03	1		94.03	ana ✓

13138.75
25% - 9854.06
155
1580.
1143.52
185.70
630
13548.28
US\$10850
05 days
✱

Date/Time: 23.11.2022 08:52

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5301549


JC NO305537657

COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O) (P) JNT CARD NO.	REGN NO: SHA4868L	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)23.11.2022 20:50	DATE/TIME IN
	YR OF MANU. 30.05.2017	TARGET DATE
	CHASSIS CODE JTDKB3FUX03557320	COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 23.11.2022
 FURE: 3P 23.11.2022

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHA4868L

CHIANG

Vehicle No.:

SHA4868L

Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard