

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 02.02.2023

MODEL: Hyundai Ioniq

VEHICLE NO.: SHC2523J

LKK-

INSURANCE: INCOME (LKS)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Fender (Blue-Drive) LH	1		\$ 26.60
	Front Fender LH	1		\$ 588.80
	SUB TOTAL			\$ 615.40
	LESS 20%			\$ 123.08
	TOTAL SPARE PARTS			\$ 492.32
	Front Fender Adv.Sticker LH	1		\$ 100.00
	Labour Charge			
	Panel Beating		600	\$ 400.00
	Spray Painting			\$ 300.00
	Check Wirings			\$ 40.00
	TOTAL LABOUR			\$ 740.00
	ESTIMATE TOTAL			\$ 1,332.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanflin 97495447
 WP 2/2/23 @ 330 pm
 2 days
 4/5 Resurvey after repair
 Tanflin @ 11/Jan/2023

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature