$51\,UBI\,AVE\,1, \#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,\,TEL:\\ (065)\,62563561\,\,FAX:\\ (065)\,62564315$

Immediate Advice

To: HSBC LIFE (SINGAPORE) PTE LTD DATE: 7/3/2023

Survey details

Date of loss	24/2/2023
Date of appointment	1/3/2023
Date of survey	1/3/2023
Location of survey	TY AUTOCARE SERVICES

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SNG 9069R
Make and Model	HONDA HRV 1.5 DX CVT
Date of registration	2/8/2017
Excess	
Market Value	\$63,000.00
Parf Rebate	\$29,731.00
Nett Loss	\$33,269.00

Repair details

	al Estimate
--	-------------

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	

Number of days of repair 7 days (est)

Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is

in the region of \$7,000.00-\$8,000.00