(06/11/13)					1		
ASS. REC. BY:	REF:	S (CTI 2300	1221	Snp3			
		SIGNMENT		1-			
From:						8 3	2010
Estimated Cost:	Date:		-	מבגרו	11 110911	ı:	1
OD/TP/WS/TP RES/OD RES/EV	A (180//80/	Type: M.Car /		Bus / Van / Lo	rry / Taxi / P	rime Move	ar /
			Trailer or				
To Inspect Vehicle No:at Workshop m/s		_ Make:		a stream	1.8	c.c	1799
of		Colour	Grey		A/C: In	sured / St	d/NI/NA
Insured:		Sp.Reading	17766	3	T/Radio: In	sured / St	d/NI/NA
		Eng/No:					
Policy No.		C/No:	JHN	7RN6880	90 .	200	0606
Claims No.		Gen. Cond: God					
	Cess:	Steering: nord					
(Client's Record) Make of Veh:		Brake: (norde			urnt or	-	
The state of the s		Modi: NII	/Rim)/ ST	D A/Rim or		-	
(Policy Condition)		Tyre Size:	F:	215 4	-5 R17		
(Policy Condition) Remark: The veh had commenced its			R:				
repair at the time of inspection	N/S O/S	BS / DUN / EXN	OVA / GY	FS / LIZA / M	IC / OHTSU	PIR / SU!	MI /
Bal. or Market Value:	"	точо / чоко	or	Good	year		
		Front			Rear		
	ent?: Yes or No			mm	R/Bal.	6	mm
	ent? : Yes or No		,	nm	L/Bal.	6	mm
	es.: Yes or No	D.O.A.			D.O.I.		
	/al.: Yes or No	Survey held at					
CA / REV / REP. / 24 HRS	A00-00 DN 200-00 - 000-00-00	Des. of Damages	: Frt / Re	ary OIS I NI	S / U/C / R	looftop or	r
Date:Person Contacted:	Vehicle: IN / OUT						
Date / Time Action / Instruction		The U/C / Ch	assis fram	e / Body Str	ucture affec	ted due to	collision.
					-		
	,						
Date/Time, File Pass to? : Preli. Rep	ort -						
) : Final Rep		ys Of Repair:					
Date/Time, File Return to?	ort Re	survey No. of 1	Trip:	Su	rvey Fee:		
	Add Fee:	7.64-1	/e	1	insportation:		
	744 F88:	: Site Insp	-	/_	S+RSSI	_	
eport Format :	 -	: Interview	-) Pt	otos		
ump Sum / I.B.I: (\$,	:Tech. Invs) 0	hers		
-	′	: Weekend	(\$)	(4)		
				1	OTAL		

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJW1722D Make & Model: Honda Stream

Chassis numbe: JHMRN68809C200606

Date of survey: Name of surveyor:

Contacts:

2 T 3 T 4 T 5 T 6 T 7 T 8 T 9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F	Tailgate Tailgate windscreen glass rubber moulding Tailgate "stream" emblem Tailgate "RSZ" emblem Tailgate outer garnish Tailgate inner handle Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock Tailgate weatherstrip Tailgate windscreen glass rubber moulding Tailgate weatherstrip Tailgate windscreen glass rubber moulding Tailgate weatherstrip Tailgate windscreen glass rubber moulding Tailgate weatherstrip	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$ \$ \$ \$ \$	956.00 89.00 47.00 55.00 193.00 32.00 479.00
2 T 3 T 4 T 5 T 6 T 7 T 8 T 9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F	Tailgate windscreen glass rubber moulding Tailgate "stream" emblem Tailgate "RSZ" emblem Tailgate outer garnish Tailgate inner handle Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1 1 1 1 1 1 1set	\$ \$ \$ \$ \$	89.00 47.00 55.00 193.00 32.00
3 T 4 T 5 T 6 T 7 T 8 T 9 T 10 T 11 T 12 T 14 T 15 F 16 F 17 F 18 F 19 F	Tailgate "stream" emblem Tailgate "RSZ" emblem Tailgate outer garnish Tailgate inner handle Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock Tailgate weatherstrip Tailgate wiper motor	1 1 1 1 1 1 1set	\$ \$ \$ \$	47.00 55.00 193.00 32.00
4 T 5 T 6 T 7 T 8 T 8 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F 19	Tailgate "RSZ" emblem Failgate outer garnish Tailgate inner handle Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1 1 1 1 1set	\$ \$ \$ \$	55.00 193.00 32.00
5 T 6 T 7 T 8 T 9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F 19 F	Tailgate outer garnish Tailgate inner handle Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1 1 1 1set	\$ \$ \$	193.00 32.00
6 T 7 T 8 T 9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F 19 F	Tailgate inner handle Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1 1 1set	\$ \$ \$	32.00
7 T 8 T 9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F 19 F 19 F	Tailgate inner trim board Tailgate inner trim board clips Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1 1set 1	\$	
8 T 9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F	Tailgate inner trim board clips Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1	\$	
9 T 10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F 19 F	Tailgate lock Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	1		80.00
10 T 11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F	Tailgate lock catch Tailgate weatherstrip Tailgate wiper motor	i	\$	119.00
11 T 12 T 13 T 14 T 15 F 16 F 17 F 18 F 19 F	Tailgate weatherstrip Tailgate wiper motor		\$	45.00
12 T 13 T 14 T 15 F 16 F 17 F 18 F	Tailgate wiper motor	1	\$	128.00
13 T 14 T 15 F 16 F 17 F 18 F		1	\$	452.00
14 T 15 F 16 F 17 F 18 F 19 F	Tailgate wiper arm	1	\$	184.00
15 F 16 F 17 F 18 F 19 F	Tailgate wiper blade	1	\$	73.00
16 F 17 F 18 F 19 F	Rear bumper B C	1	\$	812.00
17 F 18 F 19 F	Rear bumper clips	1set	\$	80.00
18 F	Rear bumper towing cover	1	\$	24.00
19 F	Rear bumper RH lower bracket	1	\$	18.00
	Rear bumper LH lower bracket	1	\$	18.0
	Rear bumper RH side retainer	1	\$	22.00
	Rear bumper LH side retainer	1	\$	22.00
	RH taillamp assy	1	\$	446.00
	RH taillamp panel	1	\$	164.00
	RH taillamp lock clip	1set	\$	28.00
	RH taillamp gasket	1	\$	25.0
	LH taillamp assy	1	\$	446.00
	_H taillamp panel	1	\$	164.00
	LH taillamp lock clip	1set	\$	28.00
	LH taillamp gasket	1	\$	25.00
	End panel Dent	1 1	\$	454.00
	End panel inner garnish	1	\$	178.00
	End panel inner garnish clips	1set	\$	60.00
	RH rear fender splash shield χ	1	\$	82.00
	RH rear fender splash shield clips	1set	\$	60.00
	RH rear fender inner trim board	1	\$	382.00
	RH rear fender inner trim board clips	1set	\$	70.00
KESKEY.	LH rear fender splash shield	1	\$	82.0
	LH rear fender splash shield clips	1set	\$	60.0
	LH rear fender inner trim board	1	\$	382.00
	LH rear fender inner trim board clips	1set	\$	70.00
	Rear comparment panel top RH cover	1	\$	218.00
	Rear comparment panel top LH cover	1	\$	218.0
	Rear compartment panel trim	1	\$	197.0
70 1	real compartment panel tilli		Ψ	101.00

		\$ 7,767.00
ľ	Parts less 20%	\$ 1,553.40
I.	Total	\$ 6,213.60

No.	Special Nett Items	Qty	Α	mount S\$
1	Tailgate centre emblem (after market)	1	\$	85.00
2	Exhaust silencer (after market)	1	\$	1,250.00
3	Exhaust silencer gasket (after market)	1	\$	67.00
4	Tailgate windscreen glass sealant	1	\$	80.00
5	Tailgate windscreen glass inner seal	1	\$	60.00
6	Tailgate reverse camera	1	\$	750.00
7	Rear bumper reverse sensor Favity	1set	\$	350.00
8	End panel joint sealant	1	\$	80.00
9	LH taillamp panel joint sealant	1	\$	50.00
10	RH taillamp panel joint sealant	1	\$	50.00
11	Rear number plate	1	\$	70.00
		Total:	\$	2,892.00

abour charges to remove, check, replace and reinstall amages bodyparts. To panel beating, cut/weld and ralign all affected panels and areas pray painting on affected areas and panels heck wiring and lighting system on affected areas	\$	-	1,400.00
amages bodyparts. To panel beating, cut/weld and salign all affected panels and areas pray painting on affected areas and panels	\$	-	1,400.00
pray painting on affected areas and panels		600	
pray painting on affected areas and panels		600	
		30	
heck wiring and lighting system on affected areas	\$	30	80.00
pply rust coating chemical on affected areas and panels	\$	40	100.00
emove and reinstall tailgate windscreen glass to assist repair	\$	80	220.00
emove and replace tailgate reverse camera to assist repair	\$	30	100.00
emove and replace tailgate inner mechansim to new tailgate	\$	50	120.00
emove and replace rear bumper reverse sensors to assist repair	\$	30	100.00
emove and replace rear inner trims, garnish and boards to assist repair	\$	40	280.00
emove and replace exhaust silencer and gasket to assist repair	\$	X	180.00
	emove and replace tailgate reverse camera to assist repair emove and replace tailgate inner mechansim to new tailgate emove and replace rear bumper reverse sensors to assist repair emove and replace rear inner trims, garnish and boards to assist repair	emove and replace tailgate reverse camera to assist repair semove and replace tailgate inner mechansim to new tailgate semove and replace rear bumper reverse sensors to assist repair semove and replace rear inner trims, garnish and boards to assist repair \$	emove and replace tailgate reverse camera to assist repair s 30 emove and replace tailgate inner mechansim to new tailgate emove and replace rear bumper reverse sensors to assist repair s 30 emove and replace rear inner trims, garnish and boards to assist repair \$ 40

(Part by Part / Lump sum) Agreed Amount:___ Working days:___

6,213.60 Spare Parts: \$ 2,892.00 4,180.00

13,285.60

Total:

4 duys Labount: \$

Total Amount: \$

2/3/23 | pm / 1 mm

4,180.00

<u> </u>
7
63D
38

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

2	Ule	
Policyholder's Signature / Date & Tirme Sketch Plan	Driver's Signature (if driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)
Sketch Plan		
		11111111
		DUNITERVITATION

Describe Circumstance of the Accident 1 was travelling straight along woodland checkpoint
out of sudden i felt an impact on my vehicle rear
portion when i got down i realised vehicle (b) collider
onto my vehicle

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Wilnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

. . . .

Singapore NRIC

Owner ID:

763D

Vehicle Details

SJW1722D

Vehicle No.: Vehicle to be Exported:

Yes

Intended Deregistration Date:

30 Jan 2023

Vehicle Make:

HONDA

Vehicle Model:

STREAM 1.8L AT RSZ

Primary Colour: Manufacturing Year: Grey 2009

Engine No.:

R18A13850606

Chassis No.:

(10/13030000

Maximum Power Output:

JHMRN68809C200606 103.0 kW (138 bhp)

Open Market Value:

\$26,187.00

Original Registration Date:

08 Mar 2010

First Registration Date:

08 Mar 2010

Transfer Count:

3

Actual ARF Paid:

\$26,187.00

Intended PARF Rebate Details

. .

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details COE Expiry Date:

07 Mar 2025

COE Category:

B - Car (1601cc & above)

COE Period(Years):

5

PQP Paid:

\$17,708.00

COE Rebate Amount:

\$7,444.00

Total Rebate Amount:

\$7,444.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jan 2023