

paper survey
Jaran / Rosul

3 Mar 2023

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110
Mobile : 9855 6879 Email : automaxsurvey@gmail.com
Registration No. 53110062J

Report Ref : TP22100018

Date: 16 JAN 2023

THL Foundation Equinebt PTE Ltd
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY
ACCIDENT OCCURED ON 11 OCT 2022

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 21 OCT 2022
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
GX5129X

1. VEHICLE PARTICULARS

Registration No : GX5129X
Model : NISSAN P/UP LOWBED
Year / Capacity : JUN 2004 / 1997 cc
Chassis No : JN1AHGD22Z0033242

Engine No : TD27736247
Mileage : 651 900 km
Colour : White

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	7.00 mm	Normal
REAR O/S :	195/50/R15	Bridgestone	7.00 mm	Normal
FRONT N/S :	195/50/R15	Bridgestone	7.00 mm	Normal
REAR N/S :	195/50/R15	Bridgestone	7.00 mm	Normal

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : ⁴~~07~~ working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GX5129X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Front Bumper Fascia	bent	\$ 950.00	\$ 950.00 <i>BT</i>
1 pc	Front Bumper Side Retainer	grazed/deformed	\$ 44.20	\$ 44.20 <i>CRA</i>
1 pc	Front Bumper Side Attachment	electronically shocked	\$ 96.40	\$ 96.40 <i>NN</i>
1 pc	Front Fender	necessary	\$ 855.00	\$ 855.00 <i>BUC</i>
1 pc	Front Support Panel	bent/distorted	\$ 620.70	\$ 620.70 <i>NN</i>
1 pc	Front Cross Member	bent/distorted	\$ 1,550.00	\$ 1,550.00 <i>NN</i>
Parts Sub-Total			\$ 4,116.30	\$ 4,116.30
Discount 30.00%			\$ 1,234.89	\$ 1,234.89
			\$ 2,881.41	\$ 2,881.41

Nett Items

1 pc	Front Grille	distorted	\$ 450.00	\$ 450.00 <i>NN</i>
1 pc	Front Grille Badge	necessary	\$ 65.00	\$ 65.00 <i>NN</i>
8 pcs	Front Grille Clips	necessary	\$ 80.00	\$ 80.00 <i>NN</i>
10 pcs	Front Bumper Clips	necessary	\$ 70.00	\$ 70.00 <i>NEC</i>
1 pc	Fog Lamp cover	electronically shocked	\$ 90.00	\$ 90.00 <i>NN</i>
1 pc	Head Lamp Assy	electronically shocked	\$ 820.00	\$ 820.00 <i>NN</i>
1 pc	Front Fender Splash Shield	wrapped/deformed	\$ 100.00	\$ 100.00 <i>CRA</i>
8 pcs	Front Fender Splash Shield Clips	necessary	\$ 80.00	\$ 80.00 <i>NEC</i>
1 pc	Front knuckle arm	bent	\$ 650.00	\$ 650.00 <i>NN</i>
1 pc	Front lower arm	bent	\$ 245.00	\$ 245.00 <i>NN</i>
1 pc	Front absorber	bent	\$ 325.00	\$ 325.00 <i>NN</i>
1 pc	Front wheel bearing hup	bent	\$ 135.00	\$ 135.00 <i>NN</i>
Parts Sub-Total			\$ 3,110.00	\$ 3,110.00
Discount 10.00%			\$ 311.00	\$ 311.00
			\$ 2,799.00	\$ 2,799.00

-Vehicle Number : GX5129X

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

Special Nett Items

1 pc	Front rim	distorted	\$ 320.00	\$ 320.00 ^{XXNW}
1 pc	Front Number Plate	wrapped/deformed	\$ 65.00	\$ 40 ⁴⁰ 65.00 ^{BT}
1 pc	Front tyre	bent/distorted	\$ 280.00	\$ 250.00 ^{XXNW}

Special Nett Sub-Total \$ 665.00 \$ 635.00

Spare Parts Total \$ 6,345.41 \$ 6,315.41

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare Parts Total c/f	\$ 6,345.41	\$ 6,315.41
1	Towing	\$ 120.00	\$ 120.00 <i>NH</i>
2	To Tuff Coat Affected Areas.	\$ 150.00	\$ 120.00 <i>40 NH</i>
3	To Remove & Replace front Undercarriage Components.	\$ 280.00	\$ 250.00 <i>NH</i>
4	To Check & Adjust Computer Wheel Alignment.	\$ 150.00	\$ 120.00 <i>NH</i>
5	To Check & Reconnect Snap Wiring.	\$ 250.00	\$ 240.00 <i>NH</i>
6	To Respray Affected Areas.	\$ 1,400.00	\$ 1,200.00 <i>400</i>
7	To Remove & Refix Air Cond Condensor, Piping, Vacuum & Top Up Gas.	\$ 150.00	\$ 120.00 <i>NH</i>
8	To Remove & Refix Radiator & Top Up Coolant.	\$ 150.00	\$ 120.00 <i>400 NH</i>
9	To Renew Damaged Parts, Straighter & Repair Front Chassis Member & Aligned All Parts.	\$ 1,600.00	\$ 1,400.00 <i>200</i>
Total		\$ 10,595.41	\$ 10,005.41

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 8,000.00

Fong
Fong Kok Heng
Qualified Appraiser



REPAIR 4 DAYS ✓

- NOT AUTHORISE

- EXCESS

- P/P OR L/S REPAIR

- SURVEY BY EDWARD TEL 62563561

- RESURVEY BEFORE PAINT FOR P/P REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GX5129X

Date: 3 Mar 2021

	LIST ITEM	NETT ITEMS	SPECIAL NETT	LABOUR
1	950	40	40	40
2	44.2	100		400
3	855	40		400
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
	\$1,849.20	\$180.00	\$40.00	\$840.00

LIST ITEM
\$1,849.20
30%
\$1,294.44

TOTAL
\$2,336.44

LUM SUM
20%
\$1,869.15

NETT ITEMS
180
10%
162