

(08/11/13) Wef
ASS. REC. BY: Amu

REF:

CS/EG/2300 2233/RVY3

YME

ASSIGNMENT

COE-2025/DEC

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 20K

Veh No:

YP 430L

Yr Regn: 2015 / DEC

Type: M.Car / M.Cycle / Bus / Van / (Lorry) Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU NHR859N

c.c 2999

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

604698

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JAA NHR 8587100355

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

15/15K15
165R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

27/02/23

D.O.I.

22/06/23

Survey held at

WASH HUNT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S & REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prelim. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YP430L ISUZU NHR85AUE4AR1

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front panel <i>JA</i>		697.00	
1	Front panel emblem "ISUZU" <i>na</i>		129.00	
1	Front panel emblem "NH" <i>na</i>		30.00	
1	Front corner top panel LH		20.00	
1	Center grille <i>cm</i>		364.00	
1	Headlamp LH <i>cm</i>		312.00	
1	Signal LH <i>cm</i>		123.00	
1	Front bumper <i>de</i>		404.00	
1	Fog lamp LH <i>de</i>		285.00	
1	Rear tail gate <i>H</i>		1958.00	
1	Rear tail gate hinge@4*\$298 <i>4-110</i>		1192.00	
1	Rear tail gate side lock latch RH <i>bt</i>		398.00	
1	Rear tail gate lower rubber stopper RH <i>ed</i>		50.00	
1	Front door LH (Repair refer to labour)		0.00	
1	Floor panel (Repair refer to labour)		0.00	
Part Items Total:			5962.00	
			-15% -894.30	
			5067.70	
SPECIAL NETT ITEMS				
1	Front panel sealant <i>na</i>		60.00	<i>40</i>
1	Center grille clips <i>na</i>		30.00	
1	Front bumper clips <i>na</i>		35.00	
1	Front car plate <i>bt</i>		35.00	
1	Rear tail gate sticker "70km/h" <i>na</i>		25.00	<i>10</i>
1	Rear tail gate sticker "13 pax" <i>na</i>		25.00	<i>10</i>
1	Rear tail gate checker plate <i>na</i>		300.00	<i>200 X</i>
1	Rivet pin (aluminium board) <i>na</i>		100.00	<i>60</i>
1	Floor panel checker plate <i>bt</i>		900.00	<i>500</i>
SN Items Total:			1510.00	
Total Parts			6577.70	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YP430L ISUZU NHR85AUE4AR1

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove & refix wiring system at accident damaged area and check for all electrical proper function	90.00	300 X
4	To perform anti-rust treatment on affected areas	90.00	60
5	To replace checker plate	600.00	300
6	To remove, replace and focus both headlamp beam	60.00	30
Labour Total :		3440.00	
TOTAL (PARTS & LABOUR):		10017.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Results
Hp 900/100 G8
9 days
4/5
22/06/23 @ 0920
Resurvey after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

477E

Vehicle No.:

YP430L

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Feb 2023

Vehicle Make:

ISUZU

Vehicle Model:

NHR85AUE4A R1

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

4JJ12E4553

Chassis No.:

JAANHR85EF7100355

Maximum Power Output:

-

Open Market Value:

\$27,220.00

Original Registration Date:

15 Dec 2015

First Registration Date:

15 Dec 2015

Transfer Count:

0

Actual ARF Paid:

\$1,361.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

14 Dec 2025

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$45,890.00

COE Rebate Amount:

\$12,792.00

Total Rebate Amount:

\$12,792.00

The information contained herein is correct as at 27 Feb 2023

OK

Isuzu NHR85A

\$24,800 Instalment \$1,126/mth

Shortlist

Loan Calculator



Overview

Financial

Photo

Research

Depreciation	\$13,690 / year
Reg. Date	16-Apr-2015 (1yr 9mths 22days COE left)
Lifespan	15-Apr-2035
Manufactured	2014
Mileage	-
Transmission	Auto
Engine Cap	2,999 cc
Curb Weight	1,760 kg
Fuel Type	Diesel
COE	\$7,009
OMV	\$30,266
ARF	\$1,514
Dereg Value	\$1,269 as of today
No. of Owners	1
Type of Veh	Truck