TAN CHONG MOTOR SALES PTE. LTD. 911, BUKIT TIMAH ROAD SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS

WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091

REFERENCE : INS/IC/LAW/0062/2023

DATE : 01-MAR-2023

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01 CITY HOUSE

S(068877)

TEL: 65073848

FAX :

ATTN: MOTOR CLAIM DEPT

OWNER'S NAME : MR CHUA HAN XIANG , JOEL

ADDRESS : BLK 345 UPPER BUKIT TIMAH ROAD

#07-12 S(588197)

TELEPHONE NO : 93851465

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : TP-GBK106Y
VEHICLE NO : SLV5265L

MODEL CODE : FRLARDWJ11USA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017

ENGINE NO : HRA2551139A
CHASSIS NO : SJNFEAJ11U2159493

MILEAGE : 1 KM

DATE IN : 01/03/2023

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : LAWRENCE

ACCIDENT DATE : 23/02/2023

01/03/2023

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL: lawrenceteo@tanchong.com

H / P: 94568832 FAX: 64697472

TAN CHONG MOTOR SALES PTE. LTD. BUKIT TIMAH W/SHOP SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV5265L

s/no	JOB CODE	NATURE OF JOB	CHARGES	SURVEYOR'S RECOMMENDATION
1	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
2	ZZ/001	REPAIR AND RENEW RH FRONT DOOR AND FENDER	1000.00	
3	ZZ/002	S/PAINT RH FRONT FENDER AND DOOR	750.00	
4	ZZ/003	TRANSFER RH WING MIRROR WIRING TO NEW DOOR	120.00	
5 :		TRANSFER RH FRONT DOOR MECHNICAL PARTS TO NEW DOOR	80.00	
		TOTAL LABOUR CHARGES	2050.00	

TAN CHONG MOTOR SALES PTE. LTD. BUKIT TIMAH W/SHOP SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV5265L

			DAMAGED	PARTS & PRI	CES	
s/no	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	FENDER-OVER, FRONT RH ARC	63810-4EA0A		- 30- 00- 30- 10- 00- 00- 00- 00- 00-		NO. 100. 000 VAL. NO. 100.
2	CANOE RIVET RH FRONT FENDER \$7.70 EA X 05	76882-0M000	38.50			
3	CLIP FENDER \$1.50 EA X 13	01553-09321	19.50			
4	FENDER-FRONT RH	F3100-4EAMB	738.90			
5	MOULDING DOOR RH FRONT	80282-4EA1B	115.20			
6	TAPE-FR DOOR,RH	80812-4EA0A	35.00			
7	DOOR-FRONT RH	Н0100-НV0МА	1258.20			
8	SUNDRIES	NPN			20.00	
	SUB TOTAL		2789.50	0.00	20.00	
	LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT0	0%)		0.00		
	GRAND TOTAL		2231.60	0.00	20.00	

2251.60

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

OVERALL TOTAL

TAN CHONG MOTOR SALES PTE. LTD. BUKIT TIMAH W/SHOP SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV5265L

TOTAL LABOUR CHARGES

2050.00

TOTAL SPARE PARTS CHARGES 2251.60

GRAND TOTAL

4301.60 * -----

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 LIABILITY : REMARKS : 0.00

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



SINGAPORE ACCIDENT STATEMENT

- IMPORTANT NOTICE

 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
 3. Information provided must be as fruthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy flability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

28/02/2023 09:08 (SGT) Both Policyholder and Actual Driver 23/02/2023 17:00 (SGT) Singapore 320 MANDAI ROAD Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLV5265L

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No Email Address

Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

No

CHUA HAN XIANG . JOEL

SXXXX154J

jconnect.joel@gmail.com (Phone) +65-93851465

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Nissan Qashqai

Private use

No - Claiming third party

Private car Auto 1200

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd. 1700094910

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

CHUA HAN XIANG . JOEL SXXXX154J 20/08/1985 Indoor

Date Of Driving Pass 26/04/2004

Driving experience 18 YEARS AND 10 MONTHS

Gender Male

Mobile Number (Phone) +65-93851465 Alt. Phone Number -

Email Address jconnect.joel@gmail.com

Address 345 UPPER BUKIT TIMAH ROAD #07.12

Address complement

Postcode 588197
Is the driver the policyholder? Yes
If No, Relationship of the Driver with the Insured -

Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver

-

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Hit and run / Vandalism / Damaged whilst parked

Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

No
Yes

Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No
Translator's name

Translator's ID

Translator's phone number

-

Translator's email - Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes

Police Station Name Bukit Timah Neighbourhood Police Centre

Police Station Phone No (Phone) +65-18004629999
Alt. Police Station Phone No (Fax) +65-64628933

Police Station Address 1 Duke Road Singapore 268914

Was notice of intended Prosecution given?

Note that the second of the s

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBK106Y
Vehicle Manufacturer Vehicle Model -

Vehicle Variant

Accident report ST0S232S0001

Page 2 of 27

 Vehicle Colour

 Vehicle Category
 Commercial vehicle

 Name of Driver

 Contact Number

 Address

 Address complement

 Postcode

 Insurance Company Name

 Nature Of Damage

 Details of property damaged in accident

 No. Of Passenger (Including Driver)

SKETCH PLAN

			.1 5			
			*			
Mark výš i s	i destes mo		ar solaje Solo	I sayatgiyakaran s	करामा <u>,</u> स्वेत्स्य स्कृतक	
Matte कुंबे	. Assistant and		and all all a	1 maigyta e s	करका (वंबर्क्ट्र)	
tarn (JA) L	. Assettes and		ar si afe Sidi	Tomostypholics	करण (बंबर,क्र.)	
*			ar kolajun do	To existant in the	करण्यात्वीसम्बद्धाः । -	
a Salahan j				A mustaget in it is	कस्याद्वीसहत्वः	
s e e e e e e e e e e e e e e e e e e e	in G. Bir Markki yarisi			A mustaget in it is	कस्या दुर्वस्य हुक् उ	
A Salah Pilili Salah pilalihar Wasan Ya	or Salah Makka yang					
Andrews Today (Inches) Windows Today (Inches)	or Garage Server Variation					
Sundayan adal Sundayan adal Sundayan Sundayan Sundayan	or San Skawa yang San San San San San Yan	ersenti i e e Geografia				
Sundania Torregan read Windows Torregan Windows Windows Windows Windows Windows	is the detector of the second	e disentat processor de la companya	er in de la companya		n de la companya de l	
Surviving Today (milant Windows) Walan Walant Wang Walant Wang Walant Wang Walant Wang Walant	igita di Kawasa ya 198 1986 - Pragasa ya 198	e disentat processor de la companya	artining and a second a second and a second	and the second of the second o	ng militar sa masa sa	
Survivial (1) Su	igita di Kawasa ya 198 1986 - Pragasa ya 198	e discount production of the second production	and the second of the second o		ng militar sa masa sa	

Last openants.

Last organisms of the second of the second

Cultiform to the Purposes.

Relating respects to the control of th

Assignment before a complete of the region of the region of \$150 of the Burgust as a section of the complete of the region of the

Sizepia Sien Tanto de Sia de la companya de la c

The factories

SKETCH PLAN #2

Andrews of the second of the s	et elland Southeth Talver
See Attached Pulice Repu	4
	and the same of th
OTHER WEHICLE NO PACE VERVE CENT Veh No Sea Veh No Sea	<u>Lo.</u> 18az - Driver Name. 18as - Driver Hame
in device	
	1

Joel Chua (HR/HRBP Trains/Plans&Train/Plans DA)

From: Michael Eng Tiso-Em (TEL/SSOO/Safety)

Sent: 27 February 2023 15:33

To: : oel Chua (HR/HRBP Trains/Plans&Train/Plans DA)

Co: Fong Chin Hong Matthew (TEL/TEL M&E)

Subject: Intedent involving G8K106Y 8: SEV526SE at SMRT Mandai Depot

To whom it may concern:

My team investigated the above incident and confirm that the incident had occurred on 23 Feb 2023 at approximately 3 45pm at SMRT Tromson East Coast Line Mandar Depot staff car park B.

For your necessary follow-up actions if any.


Thanks & Regards.

Michael Eng Branch Manager, Safety, Security & Quality Office SMRT Thomson East Coast Line

Sent from Outlook for Android

SKETCH PLAN #4





know

Ok

Your entry at 12.43pm...all good

uret.





POLICE REPORT (MP299)

Police Station Of Organ Bukit Timeh N.P.C 1 Duke's Road SINGAPORE 2689 (4 Tel No. 1800-1629999

Date/Time Report Made	Vide Report No.	Station Disay ido.
28/02/2023 07:05	yay, 1990 ya wa wana yani ya 1891 ilaya ili 1820 wa 1895 ya ka iliyika mayo layo da kakala ka ili ka wa 1800 ya 1901 ili ka wa	
Name Of Informant	Address	ин корренног отка и то иншения о отключения от вышения формация выпольной в деното отключения и и отключения о
CHUA HAN XIANG JOEL	345 UPPER SUKIT	HIMAR ROAD 507-12 SINGAPORE
ID Type / ID No.	588197 Contact No.	
NRIC NO / \$8524154J	Home/Office	iviobile
		93851465
Nationality SINGAPORE CITIZEN Occupation	Email Address JCONNECT JOEL Sex Age	@GMAIL.COM Date of Birth Race
HR MANAGER Institution/School Name	<u>Male</u> 37 Language English	20/08/1985 Chinese
Date/Time Of Incident 23/02/2023 15:45	Location Of Inciden	II D TRAIN DEPOT SINGAPORE
	779405	
Brief details.	STAFF CARPARK	£

ram a staff for SMRT working at SMRT Thomson East Coast Line Manual Depot.

On 23 February 2023 at about 5pm, I went to retrieve my vehicle bearing SLV5265L which was parked at my workplace located at SMRT Thomson East Coast Line Mandai Depot Staff Carpark 8. I then discovered dents and scratches on the driver side door and the front wheel area. I then contacted the

Signature Of Officer Recording The Report:

E / SGT 3 TEO WEL JIAN

Signature Of Interpreter.

Not applicable

Date/Time:
28/02/2023 97:05

Officer In-Charge Of Case: E. / Tangim Police Divisional Investigation Branch ! INSP (1) LALJIALIANG, ALFIAN Contact No.: 63944755

Accident report ST0S232S0001





POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20230228/2006

security officer, namely Michael England he viewed the CCTV footage and he informed me that at 12.43pm, when my vehicle first entered the depot implicated not have any damages.

I did not lodge any report till today, as SMRT was pending their investigation.

On 27/02/2023, SMRT then responded to me that another vehicle, belonging to SMRT Organization bearing GBK106Y collided to my car at 3.45pm. However, SMRT couldn't provide me the footage and particulars of the driver due to PDPA reason and informed me to fodge a police report and made a claim against GBK106Y.

I then tried to make an insurance claim, however they require a police report. I do not wish to pursue the matter and the report is just mainly for insurance claims.

Signature Of Officer Recording The Report: E / SGT 3 TEO WEI JIAN	Signature Of Informant:
Signature Of Interpreter. Not applicable	Date/Time: 28/02/2023 07:05
Officer in-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / INSP (1) LALJIALIANG, ALFIAN Contact No.: 63914755	Classification Of Case:



CERTIFICATE OF INSURANCE

Programme and the state of the state of

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Chua Han Xiang, Joel Vehicle No. : SLV5265L : 29 Dec 2022 To 28 Dec 2023 Policy No. : 1700094910-05 Period of Insurance

Engine No. : HRA2551139A Endorsement No.

: 10 Nov 2022 21:06 Issued Date Chassis No. : SJNFEAJ11U2159493

ABOUT THE COVER

: NISSAN Qashqai 1.2 DIG-Turbo Make/Model

Engine Capacity/Tonnage: 1,197.00 CC Sum Insured : Market Value First Year of Registration : 2017

Off Peak Car : No Insuring with COE/PARF : Yes Driver Restriction · NA

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$\$\$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less

Mileage Condition Age Condition : All Age Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act 1960, Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Chua Han Xiang, Joel - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1.TC AutoClinic Add: 25 Leng Kee Road Singapore 159097 67038511 67038512 67038513
- 2 TC AutoClinic Add. No.1, Sixth Lok Yang Road Singapore 628099 62622212
 3 Autolution Industrial Add: 19 Ubi Road 4 Singapore 408623 64909666
 4.Tan Chong Motor Sales Add: 913 Bukit Timah Road Singapore 589623 64694091 64694092 64694093
- 5. Tan Chong Motor Sales Add: 19 Lorong 8 Toa Payoh Singapore 319255 63570753

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from Apple App Store or Google Play Store.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: OCBC Bank Ltd

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act 1960, Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500610462

nsurance Pte.

AIG Asia Pacific

Copynaht @ 2019

Reg

ŝ

TAN CHONG CREDIT PTE LTD - LSY

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

913 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE

SINGAPORE 589623 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte, Ltd.

AIGSGMOBILEAPP

INSURER ENQUIRY Find insurer

Vehicle reg. no.

GBK106Y

Date of Accident

23/02/2023

Reset

% RESULT & RECEIPT

TP Insurer Enquiry	
Insurance	
Period of Insurance	01/04/2022 - 31/03/2023
Requested By	Eric Koh Yong Lang (Tan Chon
Requested Date	28/02/2023 09:47

Payment details

Request Amount: **\$\$1.85** GST Amount: **\$\$0.15**

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: M400017735