

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: AVS22/1661 Date: 20th Mar 2023

Our Ref: CS1/LIP23002267/Uqy3e2

M/s Liberty Insurance Pte Ltd

51 Club Street, #03-00 Liberty House Singapore 069428 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: JUQ 1005 INSURED VEHICLE: SJA 7370L ACCIDENT DATE: 17/06/2022

We thank you for your instruction on 01/03/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of JUQ 1005 from M/s Tnecniv Services.
- b) Final Repair Bill of JUO 1005 from M/s Precise Auto Service.
- c) Singapore Accident Statement of Vehicles SJA 7370L.
- d) Police Report of Vehicles JUQ 1005.
- e) Colour damaged vehicle photographs of JUQ 1005.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : JUQ 1005

Make & Model : Toyota Hiace Panel Van 2.5 (D)

Chassis Number : PN1HS02P404008098

Registration Date : 05 Sep 2011 Engine Capacity : 2494 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.