

- To resurvey before/after spray painting
- Damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and approved from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty	Particulars	Unit Price - SGD
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER Deform	610.40
2	REAR BUMPER BRACKET X	103.90
2	REAR BUMPER RETAINER X NN	84.10
2	REAR BUMPER REFLECTOR Cra	213.50
1	REAR BUMPER SPONGE X NN	180.10
1	REAR END PANEL Dent	775.10
1	REAR END PANEL TOP GARNISH Dent	201.75
1	REAR TAILLAMP X Cra	857.10
1	BOOTLID X NN	811.20
1	BOOTLID WEATHERSTRIP Deform	175.80
1	BOOTLID LOGO X	58.10
1	BOOTLID EMBLEM-VIOS X	55.93
1	BOOTLID OUTER GARNISH X	140.00
1	BOOTLID LOCK X	256.41
1	BOOTLID LOCK STRIKER X	65.00
2	BOOTLID HINGE X	110.30
1	BOOTLID INNER TRIM X	350.30
1	SPARE TYRE INNER CENTRE SPONGE X	248.40
2	SPARE TYRE SIDE SPONGE X	361.50
1	SPARE TYRE TOP BOARD X	232.89
1	FLOOR PANEL X	1100.20
		6991.98
Less 25%		1747.99
		5243.99
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP MCL	30.00
1 SET	END PANEL TOP GARNISH CLIP MCL ? MCL	30.00
1 SET	BOOTLID INNER TRIM CLIP X NN	30.00
1 SET	REVERSE SENSOR Faulty	200.00
1	JOINT SEALANT	120.00
Subtotal		410.00
Balance		5653.99
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00
2	REMOVE TRIMS & GARNISHES TO FACILITATE REPAIR	200.00
3	REMOVE & REPLACE REVERSE SENSOR	150.00
4	REMOVE & REFIT EXHAUST SILENCER	150.00
5	PANEL BEATING ON AFFECTED AREAS	1200.00
6	SPRAY PAINTING ON AFFECTED AREAS	1200.00
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00
Subtotal		3110.00
Grand total		8763.99

2427.95
606.98
1820.97

T = 3100.97
20% = 620.19
FT = 2480
= 2500X

4 days
2pm 2/3/23

By 11/2/23