



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0235/2023/EQ
DATE : 3-Mar-23
WIP : 10151


VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
7 days exclude 1 Sunday Pls refer Kee Siang.
Johnny Boo 15 Apr 23*

OWNER'S NAME : MR MOHAMMAD BIN KAMSAN
ADDRESS : 11 TAMPINES STREET 86
#15-31
SINGAPORE 528588
TELEPHONE : HP +65 98582835
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNB 7229 K**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 9/9/2021
ENGINE NO : DFY 292713
CHASSIS NO : WAUZZZGY3NA006743
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Feb-23
PLACE OF ACCIDENT : COLLYER QUAY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 7229 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$ 280.00	\$ 280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS WING MIRROR COVER.	\$ 4,000.00	\$ 1,200.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	\$ 280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,682.00	\$ 3,432.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 7229 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,778.00	\$ 1,422.40
2	FRONT BUMPER FIXING PARTS	1	\$ 307.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 137.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 281.00	
5	FRONT BUMPER AIR GUIDE - LH	1	\$ 71.00	\$ 56.16
6	FRONT BUMPER TRIM COVER - LH	1	\$ 110.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 181.00	
8	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 46.00	
9	FRONT BUMPER GUIDE SECTION - LH	1	\$ 57.00	\$ 45.60
10	FRONT BUMPER TOP COVER	1	\$ 94.00	
11	CAUTION SIGN STICKER	1	\$ 17.00	
12	AIR CONDITIONER STICKER	1	\$ 9.00	
13	HORN LOW TONE - LH	1	\$ 157.00	
14	HORN BRACKET	2	\$ 54.00	
15	HORN BRACKET - LH	2	\$ 75.00	
16	FRONT PARKING AID SENSOR - LH	1	\$ 272.00	
17	FRONT PARKING AID SENSOR - OUTER	1	\$ 286.00	
18	FRONT PARKING AID SEAL RING	4	\$ 54.00	
19	FRONT BUMPER WIRING SET	1	\$ 254.00	
20	FRONT FENDER - LH	1	\$ 1,313.00	\$ 1,050.40
SUB TOTAL SPARE PARTS		:	\$ 5,553.00	\$ 2,574.56

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 7229 K

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
		<i>C/F</i>		\$	2,574.56	
21	FRONT FENDER RIVET	3	\$	12.00	\$	9.60
22	FRONT FENDER CLOSING ELEMENT - LH	1	\$	34.00		
23	FRONT FENDER BRACKET - LH	1	\$	49.00		
24	FRONT FENDER BRACKET - LH	1	\$	38.00		
25	FRONT FENDER BRACKET - LH	1	\$	34.00		
26	FRONT FENDER BRACE - LH	1	\$	104.00		
27	FRONT FENDER ATTACHMENT PARTS	1	\$	127.00		
28	FRONT WHEEL HOUSING LINER - LH	1	\$	198.00	\$	158.00
29	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - LH	1	\$	24.00		
30	HEADLIGHT - LH	1	\$	4,323.00		
31	HEADLIGHT HOSE - LH	1	\$	29.00		
32	LIFT CYLINDER - LH	1	\$	223.00		
33	LIFT CYLINDER HOSE	1	\$	112.00		
34	FRONT EXTERIOR WING MIRROR MOUNTING - LH	1	\$	928.00	\$	742.00
35	LHS FRONT RIM (<i>Owner's invoice attached</i>)	S/N			\$	730.00
36	SUNDRIES		\$	500.00		
TOTAL SPARE PARTS		:	\$	12,288.00	\$	4,214.16
TOTAL LABOUR CHARGES		:	\$	7,682.00	\$	3,432.00
GRAND TOTAL		:	\$	19,970.00	\$	7,646.16

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-07/04/23