



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/SPF22012407/vy3-1

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: ~~CS/SPF22012407/vy3-1~~

ACCIDENT CLAIMS SECTION
(SPORE POLICE FORCE)
POLICE LOGISTICS BASE (PLB)
1 HEMMANT ROAD SINGAPORE 438675

Date: ~~12/12/2022~~ 03/03/2023

Code: SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1209G	Veh. Inspected	SLQ 3540G
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/110	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	12/12/2022 03/03/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/12/2022	Inspection Date	13/12/2022
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
