

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHD3199A

DATE: 01.03.23

MAKE HYUNDAI

MVA JUMANI

MODEL I40

DOA: 27.02.23

ALLIANZ

Qty	R	Type	Unit Price	Amount
1	REAR BUMPER ASSY <i>ara</i>			\$553.00 ✓
1	REAR BUMPER UNDER COVER <i>scr</i>			\$228.00 ✓
10	REAR BUMPER CLIPS <i>nee</i>			\$22.00 ✓
1	REAR BUMPER BEAM ?			\$428.40 <i>XIN</i>
1	REAR BUMPER SPONGE ?			\$119.50 <i>XAN</i>
SUB TOTAL				\$1,350.90
LESS 25%				\$337.72
DISCOUNTED TOTAL				\$1,013.18
BUMPER MAT <i>ivee</i>				\$50.00 NET
Labour Charge				\$50.00
PANEL BEATING				\$300.00 <i>280</i>
SPRAY PAINT				\$300.00 <i>250</i>
REMOVE / REFIX REVERSE SENSOR				\$50.00 <i>30</i>
ADVERTIEMENT LOGO - FENDER				\$200.00 <i>NEC</i>
TOTAL LABOUR				\$850.00
ESTIMATE TOTAL				\$1,913.18
				<i>20% = 1412.25</i>
				<i>282.45</i>
				<i>= 1129.8</i>
				<i>≈ 1100</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*2 days**L/S**3/3/23**J Sprm*  
*irkm*