

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melody Teoh

Date: 07 Mar 2023

**Preliminary Advice**

Vehicle No	: GBL9192H	Accident Date	: 01/03/2023
Make	: NISSAN NV350 CARAVAN	Policy No.	: DMCG22009749
Assignment Date	: 06/03/2023	Excess	: S\$0.00
Date of Inspection	: 06/03/2023	Est. Duration of Repair	: 8
Inspection At	: WOON MENG MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,059.80
Revised Amount	:S\$	5,044.80
Check Items (Estimated)	:S\$	825.50
Total	:S\$	5,870.30

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	29,949.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,051.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part Repair..  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.