



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002336/Kqy3m4 Date: 19/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 4487S	Veh. Inspected	YN 9457L	
Policy No.		Coverage (\$)	0.00	
Claim No.	KIV	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	06/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R (M)	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	-	
Chassis No.	JHHUCS3H60K014282	Colour	WHITE	
Odometer	323096 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	700R16	WEST LAKE	8 mm	
L/H Front Tyre	700R16	WEST LAKE	8 mm	
R/H Rear Tyre	700R16 (D)	WEST LAKE	8/8 mm	
L/H Rear Tyre	700R16 (D)	WEST LAKE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/02/2023	Inspection Date	17/03/2023	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a. Remarks				
A)REGISTRATION DATE: 06 OCT 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	