



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/SMR22010711/Dwy3-1

STRIDES AUTOMOTIVE SERVICES PTE LTD

60 WOODLANDS INDUSTRIAL PARK
E4SINGAPORE 757705

Ref: ~~CS3/SMR22010711/0013~~

Date: ~~20/10/2022~~ 21/02/2023

Code: SMR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 89P	Veh. Inspected	FBS 7584L
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/10/22/2069	Excess (\$)	0.00
Assign From	HUA TEN ANA MAGNAYE	Assign Date	20/10/2022 21/02/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/10/2022	Inspection Date	28/10/2022
Survey held at	TUNE IN MOTOR BLK 1016 YISHUN PARK A #01-214 SINGAPORE 768758		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.