

(08/11/13)

WEB

ASS - REC. BY: LSM

REF:

3
CS/81523002367/Rv y3

76LB

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 1448Cat Workshop m/s Hatch Sme Hatch Ltdof 1002 BUNKER MURRAY LN # 01-85Insured: GW 4255X RVS

Policy No.

Claims No. 2023 32005696FR


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

103K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 52K

13/3/23

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K - 5K) / 3 days

Veh No:

SLV 1448CYr Regn: 2017 1 DKLType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HARRIER 2.0 PREMIUM c.c 1986

Colour

WHITEA/C: Insured / Std / NI / NA

Sp. Reading

72587T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

234600162623Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

02/02/23

D.O.I.

06/03/23

Survey held at

HSHWDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 13/3/23-typist

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Report Format :

Lump Sum / L.B.I. (\$)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 762B

Vehicle Details

Vehicle No.: SLV1448C

Vehicle to be Exported: No

Intended Deregistration Date: 09 Mar 2023

Vehicle Make: TOYOTA

Vehicle Model: HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 3ZRB986047

Chassis No.: ZSU600102623

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$34,192.00

Original Registration Date: 22 Dec 2017

First Registration Date: 22 Dec 2017

Transfer Count: 0

Actual ARF Paid: \$34,869.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Dec 2027

PARF Rebate Amount: \$24,408.00

Intended COE Rebate Details

COE Expiry Date: 21 Dec 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$53,711.00

COE Rebate Amount: \$25,685.00

Total Rebate Amount: \$50,093.00

Toyota Harrier 2.0A Premium Panoramic Roof

[Overview](#)[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Ma](#)

PRIME MOTOR & LEASING



(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price **\$103,500** [Get Pre-approved Loan.](#)

Depreciation [?](#) **\$17,410 /yr**
[View models with similar depre](#)

Reg Date **29-Dec-2017**
(4yrs 9mths 19days COE left)

Mileage **N.A.**

Manufactured [?](#) **2017**

Road Tax [?](#) **\$1,196 /yr**

Transmission **Auto**

Dereg Value [?](#) **\$50,274 as of today ([change](#))**

OMV [?](#) **\$33,966**

COE [?](#) **\$48,011**

ARF [?](#) **\$39,553**

Engine Cap **1,986 cc**

Power **111.0 kW (148 bhp)**

Curb Weight [?](#) **1,610 kg**

No. of Owners [?](#) **1**