



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23002391/Kvy3m4 Date: 16/03/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLD 4536G	Veh. Inspected	SHC 5540P
	Policy No.	P10812952R00	Coverage (\$)	0.00
	Claim No.	C10020885/JY	Excess (\$)	0.00
	Assign From	MAYBIE CHUA	Assign Date	07/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTDKB3FU503092252	Colour	M. P. WHITE / RED
	Odometer	111642 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WANLI	9 mm
	L/H Front Tyre	195/65 R15	WANLI	9 mm
	R/H Rear Tyre	195/65 R15	SAILUN	8 mm
	L/H Rear Tyre	195/65 R15	SAILUN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/03/2023	Inspection Date	07/03/2023
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days	