

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202332005908 Date: 19th June 2023

Our Ref: CS6/AIS23002402/Hqy3m4

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SKF 8906Y ACCIDENT ON 03/03/2023

We thank you for your instruction on 07/03/2023.

The following vehicle information was recorded:

Registration Number : SKF 8906Y

Make & Model : Toyota Estima Aeras 2.4 A

Chassis Number : ACR507063792

Year of Registration : 2008 Engine Capacity : 2362 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.