

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Mar 2023 14:33	Clm Veh Model Changed	(204395) TOYOTA ESTIMA 2.4 AERAS (A).	[R] Samantha Tan Yong Sing
2	06 Mar 2023 14:33	Clm Created	Reg No: SKF8906Y. Policy No: SP2001808782-01. Acct Date: 2023/03/03. Claim Type: OD. Insurer: Allianz Insurance Singapore Pte. Ltd. (HQ). Workshop: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer). Created from SAS:SS2Z23360002	[R] Samantha Tan Yong Sing
3	06 Mar 2023 15:20	Clm Submitted	5332.00.	[R] Samantha Tan Yong Sing
4	07 Mar 2023 10:44	Clm Registration Modified	Excess: -> 600.00.	[I] Sharon Lim
5	07 Mar 2023 10:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):DESKTOP SURVEY	[I] Sharon Lim
6	07 Mar 2023 10:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/03/16	[I] Sharon Lim
7	07 Mar 2023 10:44	Adj Mandate Set	Approved:10000.00.Reinsp:Adj decides.	[I] Sharon Lim
8	07 Mar 2023 10:48	Assignment 1st Accessed		[A] NA MENG YAN
9	07 Mar 2023 15:27	Adj Adjuster Assigned	[None] -> Edward	[A] NA MENG YAN
10	08 Mar 2023 10:24	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2023/03/16	[A] XinYu
11	08 Mar 2023 10:24	Adj Mandate Request	Cur.Reg:4467.50:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL	[A] XinYu
12	08 Mar 2023 16:40	File Note Created	Claims - Common/Public Filenote	[A] XinYu
13	08 Mar 2023 20:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/03/16. Mandate Remarks: TO VERIFY Check Items (Estimated) :S\$ 2,404.50 LS 4 DAYS	[I] Sharon Lim
14	08 Mar 2023 20:42	Adj Mandate Set	Approved:2063.00:TO VERIFY Check Items (Estimated) :S\$ 2,404.50 LS 4 DAYS	[I] Sharon Lim

Date From   
 Date To   
 Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2926741	06 Mar 2023 14:33:51	OD/TP Case (Repairer)	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	SKF8906Y		xx.xx
2928013	08 Mar 2023 10:24:16	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKF8906Y		11.00

