



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDINGSINGAPORE 068909

Ref: CS/UOI23002412/Rvy3

Date: 07/03/2023

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 4251E	Veh. Inspected	SLJ 2710B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KATIE LEE	Assign Date	07/03/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date		Inspection Date	07/03/2023
Survey held at	48 Toh Guan Road East, Enterprise Hub, #02-146		
Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--