

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23002420/Uwy3	
	75 BRAS BASAH FINCOME CENTRES	ROAD SINGAPORE 189557		Date:	07/03/2023	
				Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMP 7384H	Veh. Inspected		SKU 4373G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1212675-001	Excess (\$)		0.00	
	Assign From	JESS TOH	Assign Date		07/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
5. General Information						
	Accident Date	02/03/2023	Inspection Dat	е	07/03/2023	
	Survey held at	SPEEDWERKZ PTE LTD				
		1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883				
5a.	5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						