



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Ref: CS/INC23002422/Awy3 Date: 07/03/2023 Code: INC	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJK 769P	Veh. Inspected	SLK 8453Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1211907-002	Excess (\$)	0.00
	Assign From	JESS TOH	Assign Date	07/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	28/02/2023	Inspection Date	07/03/2023
	Survey held at	1 KAKI BUKIT AVENUE 6 #02-25 AUTOBAY @ KAKI BUKIT		
	Repairer	LC AUTOMOTIVE		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			