

FC GARAGE

NO 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-04 Singapore 415875

Tel: 65 90110243

CO. Reg. No.: 53409207A

Model : Nissan NV 350
 Registraion No : GBH 6536 R
 Chassis No: JN1MC2E26Z0008962
 Year of Manufacturing: 2017

S/No	Qty	Items	Unit	Amount
1	1	Tailgate <i>Den +</i>	\$ 2,704.40	\$ 2,704.40 2101 ✓
2	1	Tailgate Logo <i>Me</i>	\$ 82.50	\$ 82.50 ✓
3	1	Tailgate Emblem - NV350 <i>Me</i>	\$ 114.70	\$ 114.70 94 ✓
4	1	Tailgate Emblem - URVAN <i>Me</i>	\$ 82.50	\$ 82.50 ✓
5	1	Tailgate Lock <i>3X nn</i>	\$ 387.40	\$ 387.40
6	1	Tailgate Inner Lock Actuator <i>X nn</i>	\$ 480.90	\$ 480.90
7	1	Tailgate Outer Handle <i>X nn</i>	\$ 71.50	\$ 71.50
8	1	Tailgate Weatherstrip <i>CV +</i>	\$ 283.90	\$ 283.90 134 ✓
9	1	Tailgate Windscreen Moulding <i>Me</i>	\$ 109.70	\$ 109.70 ✓
10	1	Tailgate Inner Trim Board <i>X nn</i>	\$ 285.60	\$ 285.60
11	1	Tailgate Chrome Piece <i>X nn</i>	\$ 284.70	\$ 284.70
12	1	Rear Bumper <i>Reform</i>	\$ 832.50	\$ 832.50 667 ✓
13	2	Rear Bumper Retainer <i>X nn</i>	\$ 20.30	\$ 40.60
14	2	Rear Bumper Bracket <i>X nn</i>	\$ 20.30	\$ 40.60
15	1	Rear Bumper Reinforcement <i>? X nn</i>	\$ 188.90	\$ 188.90
16	1	Tail Lamp (RH) <i>iron</i>	\$ 258.90	\$ 258.90 ✓
17	1	Tail Lamp (LH) <i>X nn</i>	\$ 258.90	\$ 258.90
18	1	Rear End Panel Outer <i>DD</i>	\$ 212.80	\$ 212.80 ✓
19	1	Rear End Panel Inner <i>Den +</i>	\$ 561.60	\$ 561.60 ✓
20	1	Rear End Panel Top Moulding <i>DD</i>	\$ 268.70	\$ 268.70
21	1	Rear Step Panel <i>Reform</i>	\$ 346.60	\$ 346.60 178 ✓
22	1	Rear Floor Panel <i>Den + 2 X</i>	\$ 2,267.50	\$ 2,267.50

4482
 -10%
 4033.80

-10% -20%
 Total for spare parts

\$	10,165.40
\$	2,033.08
\$	8,132.32

Special Nett

1	1	Tailgate Glass Sealant	\$ 80.00	\$ nec 80.00 50
2	1	Tailgate Glass Foam Tape	\$ 70.00	\$ nec 70.00 30
3	1	Tailgate Sticker - 70km/h	\$ 15.00	\$ 15.00 Me
4	1	Rear No. Plate	\$ 50.00	\$ 50.00 X nn
5	1	Rear Bumper Clip set	\$ 50.00	\$ 30 50.00 Me
6	1	Rear Reverse Sensor <i>Faulty</i>	\$ 300.00	\$ 300.00 200

325

Total for SP	\$	565.00
Sub-Total for Parts :	\$	8,697.32

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,500.00 600 750
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,800.00 600
3		Apply rust proofing on the adjacent panels	\$	80.00 40
4		To supply under coating / putty on parts replaced	\$	80.00 X
5		To perform water seepage test after repair	\$	80.00 X
6		Disconned and check electrical wiring, harness, wire socket	\$	80.00 30
7		To remove and refit rear windscreen	\$	180.00 80
8		Dismantle and transfer door fittings and mechanism to new door/facilitate repair	\$	150.00 50

1550

TOTAL AMOUNT : \$ 3,950.00
OVERALL COST: \$ 12,647.32

5908.80

5 days

L/S - 4727.04
= 4750

L/S

7/3/25

S/ir

430pm

90097659