

ASS. REC. BY:

REF:

AG2/230024271K_n

Kenneth

ASSIGNMENT

From:

Date:

Veh No:

PMX 8151P Yr Regn: 05.18

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / IP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Honda Jazz C.C. 1318

at Workshop m/s

Colour

M. Yellow A/C: Insured / Std / NI / NA

of

Sp. Reading

103307 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modl: Nil / SRim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

R:

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0031557
Boh Qi Jie Ryan Nathan

Page 1 of 2
Your ref. TP-SLT 2314J AGI
Job No. 73430
Our ref. 23.03.09
Payment
Date 7/3/2023

Attn

Vehicle No SMX 8151P
Vehicle Model : Honda Jazz
Accident on ... 5/3/2023

Not Notified
Accident B4 repair
4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet	976.80	20.00	<i>RM</i> 781.44 ✓
1.00	Pc	Front bumper	901.70	20.00	<i>RM</i> 721.36 ✓
1.00	Pc	Front bumper side retainer RH	18.40	20.00	14.72 ?
20.00	Pcs	Front bumper clips	3.00	20.00	<i>RM</i> 48.00 ✓
1.00	Pc	Front bumper centre grille side moulding RH	51.00	20.00	40.80 ?
1.00	Pc	Front radiator grille	343.40	20.00	<i>CM</i> 274.72 ✓
1.00	Pc	Front grille top chrome moulding	232.80	20.00	<i>CM</i> 186.24 ✓
1.00	Pc	Front grille moulding	249.40	20.00	<i>RM</i> 199.52 ✓
1.00	Pc	Front grille logo emblem	<i>RM</i> 27.40	20.00	21.92 ✓
1.00	Pc	Front fender inner shield RH	<i>N.C (CM)</i> 110.50	20.00	88.40 X
1.00	Pc	Front number plate base	85.40	20.00	<i>RM</i> 68.32 ✓
1.00	Pc	Front headlamp lower beam LH	44.70	20.00	35.76 ?

Special nett item:

1.00 Pc Front number plate

35.00

RM 35.00 ✓

Labour & Misc:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，提供多种款式的车身及给予快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0031557
Boh Qi Jie Ryan Nathan

Page 2 of 2
Your ref. TP-SLT 2314J AGI
Job No. 73430
Our ref. 23.03.09
Payment
Date 7/3/2023

Attn

Vehicle No SMX 8151P
Vehicle Model : Honda Jazz
Accident on ... 5/3/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To straighten front body, to knock dents on front support panel and renew of parts	400.00		400.00 ✓
1.00		To spray paint	600.00		600.00 ⁵⁰⁰

Sub-Total 3,516.20
GST 8.00% 281.30
Total S\$ 3,797.50

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。外，还有先进的 SAICO Deluxe 喷漆烘炉。
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support body system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/03/2023 17:22 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	05/03/2023 09:50 (SGT)
Exact Location of Accident	Tampines Street 73, Singapore
Additional Location Information	Pinevale Condo
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX8151P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Boh Qi Jie Ryan Nathan
NRIC No	SXXXX722B
Email Address	ryanboh1996@gmail.com
Mobile Phone No	(Phone) +65-97630810
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Jazz
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1300

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	A 300570965 QMX

DRIVER

Name of Driver	Boh Qi Jie Ryan Nathan
NRIC No	SXXXX722B
Date Of Birth	27/04/1996
Occupation	Indoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

[Signature]

6/3/23

Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Lim Lai Foong

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

At 9:50am, 5 March 2023, I was going to Private condominium to pick up my fiancé. As I entered the gantry, there was a yellow CHR Toyota (5LT2314J) in front of me, talking to the security guard at the gantry. Her car accelerated backwards into my stationary vehicle and there was a large impact. I came out of the car & inspected the vehicle, and noted that my front bumper was dislodged from the vehicle. The license plate was damaged & there was a dent on the hood of the vehicle, on top of other damages to the car. The driver of the CHR is Wang Ying (5878446C) and she informed me that she assumed that she was Indrive & not reverse when she proceeded to accelerate.

Declaration

(We declare the foregoing particulars are true in every respect)

 6/3/23

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
Date & Time

 Lim Lai Foong

Witnessed by Reporting Centre Personnel
(Name as in NRIC/D card)