

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 2016058782)
60 JALAN LAM HUAT CARROS CENTRE
#05-68 (S737869)

Not Notified
11 Day @
Penny After 6 days

TO	: ALLIANZ	DATE	: 8-Mar-23
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
VEHICLE DETAILS			
	:	VEHICLE NO	: SNB9273T
	:	MODEL	: LEXUS RX200
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Rh</i>	1	\$ 2,415.00	\$ 2,415.00
2	TAILGATE LOGO <i>Rh</i>	1	\$ 153.00	\$ 153.00
3	TAIL GATE EMBLEM "LEXUS" <i>Rh</i>	1	\$ 78.00	\$ 78.00
4	TAIL GATE EMBLEM "RX200T" <i>Rh</i>	1	\$ 78.00	\$ 78.00
5	TAILGATE WEATHERSTRIP <i>Rh</i>	1	\$ 259.60	\$ 259.60
6	TAILGATE INNER TRIM BOARD <i>Rh</i>	1	\$ 387.10	\$ 387.10
7	TAILGATE WINDSCREEN GLASS <i>Shatter</i>	1	\$ 1,598.00	\$ 1,598.00
8	TAILGATE WINDSCREEN MOULDING <i>Rh</i>	1	\$ 389.10	\$ 389.10
9	TAILGATE TOP SPOILER <i>CM1</i>	1	\$ 1,789.00	\$ 1,789.00
10	REAR FENDER RH <i>Rh</i>	1	\$ 1,139.60	\$ 1,139.60
11	REAR FENDER QUARTER GLASS RH <i>with M4</i>	1	\$ <i>Net</i> 954.00	\$ 954.00

TOTAL PRICE	\$ 8,240.40
LESS 10%	\$ 824.04
SUB TOTAL PRICE	\$ 7,416.36

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET <i>nn</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER SIDE LIP CLIPS SET <i>nn</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER PAD CHROME <i>Rh</i>	1	\$ 1,200.00	\$ 1,200.00
4	REAR FENDER INNER TRIM CLIPS STE <i>Rh</i>	1	\$ 60.00	\$ 60.00

5	REAR WINDSCREEN SEALANT	1	\$ 150.00	\$ 150.00
---	-------------------------	---	-----------	-----------

SUB TOTAL PRICE \$ 1,490.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$800.00		600
2	TO SPRAY PAINT AFFECTED AREA	\$800.00		660
3	TUFF COAT	\$250.00		300
4	WIRING CHECK	\$50.00		200
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$400.00		1200
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	~	X
7	REMOVE AND REFIX REAR WINDSCREEN	\$250.00		1800
8	CONDUCT WATER LEAKAGE TEST	\$80.00		200

TOTAL \$2,710.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,906.36
TOTAL LABOUR COST : \$ 2,710.00
TOTAL REPAIR COST : \$ 11,616.36

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

(re:)