

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAI	NCE PTE LTD	Ref:	CS/LIP23002438/Uny3e2	
	51 CLUB STREET LIBERTY HOUSES	, #03-00 SINGAPORE 069428	Date:	11/04/2023	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJS 7816Z	Veh. Inspected	SLR 7952U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	IVS23/0491	Excess (\$)	0.00	
	Assign From	ANDY SEAH	Assign Date	07/03/2023	
2.	. Vehicle Particulars & Condition				
	Make & Model	KIA NIRO HYBRID (A)	c.c	1580	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.	KNACC81CVJ5104701	Colour	BLUE	
	Odometer	104286 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	MICHELIN	7 mm	
	L/H Front Tyre	205/60 R16	MICHELIN	7 mm	
	R/H Rear Tyre	205/60 R16	MICHELIN	7 mm	
	L/H Rear Tyre	205/60 R16	MICHELIN	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/03/2023	Inspection Date	07/03/2023	
	Survey held at	ZOOM AUTOWERKS PTE LTD			
		130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
5a.	•	Remarks			
	A)REGISTRATION DATE: 29 AUG 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				