



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel. 6844 1184

TP Liberty.
Hui Ray.

Vehicle No. SNF2331J

TOYOTA NOAH

ZWR800501136

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR TAILGATE <i>Dented</i>	1	\$ 2,542.00	\$ 2,542.00 1812.
2	REAR TAILGATE "HYBRID" <i>new</i>	1	\$ 85.05	\$ 85.05
3	REAR TAILGATE CENTRE CHROME TRIMING <i>new</i>	1	\$ 520.00	\$ 520.00
4	REAR TAILGATE INNER LOCK MECHANISM <i>new</i>	1	\$ 530.00	\$ 530.00
5	REAR TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 332.50	\$ 332.50
6	REAR TAILGATE DAMPER LH & RH @300.00 <i>new</i>	2	\$ 300.00	\$ 600.00
7	REAR BUMPER <i>Dented</i>	1	\$ 1,745.30	\$ 1,745.30 885
8	REAR BUMPER TOW COVER <i>new</i>	1	\$ 89.25	\$ 89.25
9	REAR BUMPER SIDE RETAINER @ 155.20 <i>new</i>	2	\$ 155.20	\$ 310.40
10	REAR BUMPER KEYLESS ANTENNA <i>new</i>	1	\$ 255.10	\$ 255.10 145.

TOTAL PRICE: \$ 7,009.60

LESS 25% \$ 1,752.40

SUB TOTAL PRICE: \$ 5,257.20

3027-05
2270-28

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>3 new</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>3 new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
5	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
6	REAR END PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
7	BOOTLID INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
8	REVERSE CAMERA <i>new</i>	1	\$ 350.00	\$ 350.00
9	REAR WINDSCREEN SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00

TOTAL: \$ 650.00

290

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 600.00	600 500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 700.00	700 600	
3	WIRING CHECK	\$ 150.00	150 30	
4	TO APPLY TUFF COAT	\$ 300.00	300 30	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	100 50	
9	TO REMOVE AND REFIT REAR WINDSCREEN	\$ 180.00	180 120	

TOTAL: \$ 2,030.00

1380

ESTIMATE REPORT

TOTAL PARTS COST:	\$	5,907.20
TOTAL LABOUR COST:	\$	2,030.00
TOTAL REPAIR COST:	\$	7,937.20

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

Adrian Ling.
2/s 08/03/23.

4 Days.

total: 3890.28

4/s: 3.1K

3.1K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: