

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0242/2023/EQ
DATE : 6-Mar-23
WIP : 10491

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM TEO WENG
ADDRESS : 42 SPRINGSIDE AVENUE
SINGAPORE 786990

TELEPHONE : HP +65 98624822
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210110869
VEHICLE NO : **SNB 7686 Z**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 14/9/2021
ENGINE NO : CZD C48819
CHASSIS NO : WAUZZZF35M1152923
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Mar-23
PLACE OF ACCIDENT : 42 SPRINGSIDE AVENUE OUTSIDE MY HOUSE,
ALONG THE ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 7686 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00 280 ✓	
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00 500 ✓	
3	550 300 TO RESPRAY RHS FRONT DOOR AND DOOR COVER.	\$	1,600.00 850 ✓	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		: \$	<u><u>3,392.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 7686 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH <i>Dented</i>	1	\$ 3,203.00	✓ <i>2562.40</i>
2	FRONT DOOR OUTER SEAL - RH <i>new</i>	1	\$ 196.00	✓ <i>156.40</i>
3	FRONT DOOR CATCH - RH <i>new</i>	1	\$ 141.00	? <i>X</i>
4	FRONT DOOR COVER - RH <i>new</i>	1	\$ 413.00	✓ <i>330.40</i>
5	SUNDRIES <i>new.</i>		\$ 300.00	? <i>4.16</i> ✓
TOTAL SPARE PARTS		:	\$ 4,253.00	
TOTAL LABOUR CHARGES		:	\$ 3,392.00	
GRAND TOTAL		:	\$ 7,645.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *06/03/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Xbe Authorised, 23 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT