



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. GBD 6325D

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRONT BUMPER	DEFORMED	495.60
1	FRONT RH BUMPER RETAINER	DEFORMED	23.60
1	RHS HEAD LAMP	MISSING	649.00
1	RHS FOG LAMP	CRACKED	271.40
1	FRONT RH FENDER	BENT	590.00
1	FRONT SUPPORT PANEL	CRACKED	619.50
1	ABS PUMP ASSY	CRACKED	4,130.00
1	ABS MODULE WIRING HARNESS	NOT NECESSARY	-
1	BONNET COVER	BENT	920.40
1	AIR CLEANER	CRACKED	106.20
1	WIPER TANK	DEFORMED	41.30
			7,847.00
	<u>LABOUR</u>		
	REMOVE, REPLACE & SPRAY PAINT FOR FRONT BUMPER INCLUDING REPLACING FRONT RH BUMPER RETAINER. (5 MAN-HOUR)		340.00
	REMOVE, REPLACE & WIRING FOR RHS HEAD LAMP. (0.5 MAN-HOUR)		34.00
	REMOVE, REPLACE & WIRING FOR RHS FOG LAMP. (0.25 MAN-HOUR)		17.00
	REMOVE & REPLACE FRONT SUPPORT PANEL. (2 MAN-HOUR)		136.00
	REMOVE, REPLACE & SPRAY PAINT FOR FRONT RH FENDER. (4 MAN-HOUR)		272.00
	REMOVE, REPLACE & SPRAY PAINT FOR BONNET COVER. (4 MAN-HOUR)		272.00
	REMOVE & REPLACE AIR CLEANER. (0.5 MAN-HOUR)		34.00
	REMOVE & REPLACE WIPER TANK. (0.25 MAN-HOUR)		17.00
	REMOVE & REPLACE ABS PUMP ASSY. (NPA)		-
	REMOVE & REPLACE ABS MODULE WIRING HARNESS. (NPA)		-
			1,122.00
	GRAND TOTAL		8,969.00

Report Ref No. CS/INC23002449/Tqy3e2



RECOMMENDED COST OF REPAIRS (UN-CONFIRMED)	8,969.00
---	-----------------

Report Ref No. CS/INC23002449/Tqy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.