

# MBM WHEELPOWER PTE. LTD.



YOUR REF.:

OUR REF.: SLA9724M

TO: INDIA INTERNATIONAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

SUPPLEMENTARY FOR VEHICLE NO.: SLA9724M

DATE: 21/3/2023  
FROM: Lee Shirley  
FAX: 64525333  
CONTACT: 86865188  
MAKE & MODEL: TOYOTA HARRIER 2.0 PREMIUM  
CHASSIS NO.: ZSU600073557  
ENGINE NO.: 3ZRB738573  
YEAR MADE: 2016  
ACCIDENT DATE: 4 March 2023

| NO. | DESCRIPTION                                 | PART NO. | QTY.         | LIST PRICE  |
|-----|---------------------------------------------|----------|--------------|-------------|
| 1   | CONDENSER RELAY                             |          | 1            | \$ 210.00 ✓ |
| 2   | FRONT RADIATOR SIDE AIR GUIDE PLATE REAR RH |          | 1            | \$ 115.00 ✓ |
| 3   | HEADLAMP BEAM RH                            |          | 1            | \$ 115.00 ✓ |
| 4   | SUPPORT PANEL TOP GARNISH CLIP              |          | 10           | \$ 30.00 ✓  |
|     |                                             |          | TOTAL:       | \$ 470.00   |
|     |                                             |          | LESS 25%:    | \$ (117.50) |
|     |                                             |          | PARTS TOTAL: | \$ 352.50   |
|     |                                             |          | 8% GST:      | \$ 28.20    |
|     |                                             |          | GRAND TOTAL: | \$ 380.70   |

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

T 6262 8888 F 6452 5333

COMPANY REG. NO.: 200204110W