

Xin Yu (LKK Auto)

From: Xin Yu (LKK Auto)
Sent: Monday, March 20, 2023 8:58 AM
To: 'shirley.lee@mbmwheelpower.com.sg'
Cc: SUR
Subject: RE: Own Damage CLaims for Vehicle No.: SLA9724M, Toyota Harrier DOA 04/03/2023
Attachments: SLA 9724M Supplementary Estimate.PDF

Dear Shirley,

Please proceed with the supplementary as attached with our surveyor marking.

Best Regards,

Xin Yu | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | fax: 6256-4315 | email: xinyu@lkkauto.com / sur@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Xin Yu (LKK Auto)
Sent: Monday, March 13, 2023 10:33 AM
To: shirley.lee@mbmwheelpower.com.sg
Subject: Own Damage CLaims for Vehicle No.: SLA9724M, Toyota Harrier DOA 04/03/2023

Dear Shirley,

As instructed by our client, please proceed to repair the insured vehicle **SLA 9724M (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Xin Yu | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | fax: 6256-4315 | email: xinyu@lkkauto.com / sur@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)