Date: 08/05/2023



 $51~\mathrm{UBI~AVE~1}, \#02\text{-}25~\mathrm{PAYA~UBI~INDUSTRIAL~PARK}, \mathrm{SINGAPORE~408933~TEL:} \\ (065)~62563561~\mathrm{FAX:} \\ (065)~62564315$ 

#### **Immediate Advice**

To: HSBC LIFE (SINGAPORE) PTE LTD

#### **Survey Details:**

Date of loss	05/03/2023
Date of appointment	08/03/2023
Date of survey	09/03/2023
Location of survey	1Axis Workshop Pte Ltd

## Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SKU5759X
Make and Model	MERCEDES BENZ CLA 180 ( 1595 CC )
Date of registration	03/08/2015
Market Value	\$ 65,000.00
Parf Rebate	\$ 31,369.00
Nett Loss	\$ 33,631.00

## Repair details:

# Proposed/Revised repair cost:

Parts	\$ 37,611.19
Check items (estimate)	NIL
Labour	\$ 4,250.00
Total	\$ 41,861.19
Lump Sum(if applicable)	\$ 32,000.00

Number of days for repair	18.0
---------------------------	------



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$ 

## Remarks:

LIABILITY 100% - BOLA 28.	CHAIN COLLISION - SMY6053Y ( OI ) > SKU5759X ( TP
) > SNC7074J > SNB5695K.	

# Mandate:

Liability(TP)	100%
Proposed repair cost (WITH 8% GST)	\$ 34,560.00
Loss of Use (21DAYS X \$60.00)	\$ 1,260.00
Loss of Rental	NIL
Loss of Income	NIL
LTA/GIA search fees	\$ 26.75
Others	NIL
Proposed Total	\$ 35,846.75