



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA			Ref: CC4/HSB23002499/Kpa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7345Z	Veh. Inspected	SKW 4119P	
Policy No.	P2478220	Coverage (\$)	0.00	
Claim No.	S3M04K9M	Excess (\$)	0.00	
Assign From		Assign Date	09/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO V40 T2 (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	YV1MV28H0G2297610	Colour	METALLIC GOLD	
Odometer	50609 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	7 mm	
L/H Front Tyre	205/55 R16	PIRELLI	7 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2023	Inspection Date	09/03/2023	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	