

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI ELANTRA

Engine/Chassis No.: KMHD841CMJU767552


Date of accident: 05.03.23

Damaged area: Rear

Date: 28/03/2023

Claim Type: TP

VRN: SMF4023Y



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear Bumper	1	\$ 983.00	\$ 983.00
2	Rear Bumper diffuser	1	\$ 467.00	\$ 467.00
3	Rear Bumper lower cowl	1	\$ 314.00	\$ 314.00
4	Rear Bumper reflector	2	\$ 255.00	\$ 510.00
5	Rear Bumper splash guard	2	\$ 95.00	\$ 190.00
6	Rear Bumper reinforcement support bracket	5	\$ 36.00	\$ 180.00
7	Rear Bumper reinforcement	1	\$ 659.00	\$ 659.00
8	Rear Bumper reinforcement side bracket	2	\$ 129.00	\$ 258.00
9	Rear bumper side retainer	2	\$ 65.00	\$ 130.00
10	Rear licence plate lamp	2	\$ 143.00	\$ 286.00
11	Rear bumper licence plate base	1	\$ 59.00	\$ 59.00
12	End panel	1	\$ 732.00	\$ 732.00
13	End panel top garnish	1	\$ 177.00	\$ 177.00
Subtotal				\$ 4,945.00
List discount				20.00%
Total				\$ 3,956.00

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear Bumper clips	12	\$ 4.50	\$ 54.00
2	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
3	End panel top garnish clips	8	\$ 4.50	\$ 36.00
4	Reverse sensor	1	\$ 280.00	\$ 280.00
5	End panel sealant	1	\$ 100.00	\$ 100.00
6	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 575.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To remove, replace reverse sensors and check for proper function.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To rust proof accident affected portions.	0.5	\$ 100.00
Total labour			\$ 2,450.00
Estimate Grand Total			\$ 6,981.00