



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23002508/Rvy3e2

Date: 12/07/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 9987Z	Veh. Inspected	SMY 3700H
Policy No.	D-23100428MFBP/1	Coverage (\$)	0.00
Claim No.	D23000822MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	09/03/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS PLUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTDZS3EU80J058656	Colour	GREY
Odometer	200250 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	DUNLOP	6 mm
L/H Front Tyre	205/60 R16	DUNLOP	6 mm
R/H Rear Tyre	205/60 R16	DUNLOP	6 mm
L/H Rear Tyre	205/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/03/2023	Inspection Date	09/03/2023
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**