



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002543/Wny3e2 Date: 21/06/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 7104K	Veh. Inspected	SMN 8982K	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0766	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	10/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	SEAT TOLEDO	c.c	1395	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	VSSZZZNHZK1010669	Colour	BLUE	
Odometer	71403 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	KAPSEN	6 mm	
L/H Front Tyre	205/45 R17	KAPSEN	6 mm	
R/H Rear Tyre	205/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	205/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2023	Inspection Date	10/03/2023	
Survey held at	VERTEX EURO MOTORS 3 UBI ROAD 4 SINGAPORE 408608			
5a. Remarks				
A)REGISTRATION DATE: 16 MAY 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	