

VERTEX EURO MOTORS PTE LTD

3 Ubi Road 4 Singapore 408608
TEL: (+65) 6742-9368 FAX: (+65) 6742-5281
RCB NO:201535856D

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

Estimate No: WQT1604388
Date: 08 Mar 2023
Policy No:
Veh Reg No: SMN8982K
Make/Model: SEAT TOLEDO 1.4 TSI
125 STYLE 7AT
Chassis No: VSSZZZNHZK1010669
Engine No: CZCA15116
Reg. Date: 16/05/2019

ATTN:

Your Ref No: SMN8982K
Claim Type:
Accident Date:

Estimate Repair Cost to Vehicle No :SMN8982K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Others				
1 DOOR RR LH	3,250.00	1 PCS	3,250.00 OT	
2 D/RUBBER LH RR	525.00	1 PCS	525.00 NRC	
3 DOOR MLDG RR LH OTR	340.00	1 PC	340.00 NRC	
4 D/RUBBER RR LH OTR	380.00	1 PCS	380.00 NRC	
5 W/GUIDE LH RR	285.00	1 PCS	285.00 NRC	
6 SUNDRIES	120.00	1	120.00 \$20	
7 LABOUR TO REPLACE, REMOVE & REINSTALL RR LHS DOOR ASSY, DOOR MLDGS RR LHS, DOOR SEALS & READJUST RR LHS DOOR ASSY	2,500.00	1	2,500.00 \$600	
8 LABOUR TO RESPRAY REAR LHS DOOR, INNER DOOR PANEL ASSY, FRT LHS DOOR, UNDER NET PANEL & RR FENDER ASSY	2,000.00	1	2,000.00 \$600	
9 LABOUR TO REMOVE AND TRANSFER REAR LHS WINDOW GLASS, DOOR LOCK ASSY, DOOR LOCK CONTROL MODULE, DOOR RUBBER SEALS, DOOR TRIM ASSY, DOOR HINGE UPPER AND DOWN & DOOR WIRING HARNESS WITH DOOR SWITCH	700.00	1	700.00 \$700	
10 LABOUR TO CARRY OUT DIAGNOSTIC CHECK	300.00	1	300.00 \$150	
11 LABOUR TO CALIBRATE & RE-ADAPT RR LHS DOOR LOCK SYSTEM & REPROGRAMMING RR DOOR GLASS AND SAFETY LOCK	350.00	1	350.00 \$200	
12 LABOUR TO INSTALL RR RHS DOOR SOLAR FILM	420.00	1	420.00 X \$6,650	
			11,170.00	11,170.00
Total			S\$ 11,170.00	\$6,650
Add GST @ 8%				893.60
Total Amount Payable				S\$ 12,063.60
TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SIXTY THREE AND CENTS SIXTY ONLY				\$7543.6

03 days

Akid 87005631
gil 10103123
1156hrs

For VERTEX EURO MOTORS PTE LTD



AUTHORIZED SIGNATURE