

TSL AUTO GARAGE

1 KAKI BUKIT AVENUE 6 #01-08

AUTOBAY @KAKI BUKIT SINGAPORE 417883

TP MSBC
Xiao Chan.

Vehicle No. SCR76B

MERCEDES BENZ GLA200

WDC1569432J606244

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR BUMPER <i>Del'd</i>		1266.00	✓
2	REAR BUMPER SIDE HOLDER RH <i>new</i>		91.00	+
3	REAR BUMPER LOWER GARNISH <i>Del'd</i>		604.00	✓
4	REAR BUMPER SIDE SENSOR RH <i>Del'd</i>		255.00	✓
5	REAR BUMPER SENSOR HOLDER @25 <i>new</i>		150.00	✓
6	REAR RH FENDER <i>Regis</i>		2255.00	+
7	REAR RH FENDER ARC GARNISH <i>cut</i>		286.00	+
8	REAR RH FENDER INNER SHIELD <i>new</i>		248.00	+
9	REAR RH DOOR <i>Del'd</i>		2191.00	✓
10	REAR RH DOOR LOCK <i>new</i>		355.00	+
11	REAR RH DOOR WEATHERSTRIPE <i>new</i>		309.00	+
12	REAR RH DOOR INNER TRIM BOARD <i>new</i>		954.00	+
13	ROCKER PANEL OUTER SKIRTING <i>Del'd</i>		592.00	✓
14	REAR RH WHEEL RIM <i>cut</i>		1149.00	680(SW).
15	REAR RH SHOCK ABSORBER <i>2</i>		529.00	+
16	REAR RH KNUCKLE ARM <i>new</i>		1265.00	+
17	REAR RH LOWER ARM <i>new</i>		561.00	+
18	REAR RH WHEEL HUB C/W BEARING <i>Damaged</i>		425.00	✓
		5769		
		5192.10		
		S.N: 680		
		less	10%	10%
			13485.00	
			1348.50	
			12136.50	
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS <i>new</i>		30.00	✓
2	REAR RH FENDER ARC GARNISH CLIPS <i>new</i>		20.00	✓
3	REAR RH FENDER INNER SHIELD CLIPS <i>new</i>		30.00	+
4	REAR RH DOOR INNER TRIM BOARD CLIPS <i>new</i>		30.00	+
5	ROCKER PANEL OUTER SKIRTING CLIPS <i>new</i>		30.00	✓
6	REAR RH TYRE <i>new</i>		350.00	+
		80		
Total Parts			490.00	

SCR76B.

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1200.00 500	
2	SPRAY PAINTING	1200.00 400	
3	WIRING	100.00 30	
4	TO APPLY TUFF COAT	150.00 30	
5	TO REMOVE UPHOLSTERY	150.00 x	
6	TO REMOVE REVERSE SENSOR	100.00 50	
7	TO TRANSFER REAR DOOR FITTINGS	150.00 60	
8	TO REMOVE REAR UNDERCARRIAGE	350.00 80	
9	TO PERFORM WHEEL ALIGNMENT	150.00 80	
10	TO PERFORM DIAGNOSTIC TEST	200.00 x	
	Labour Total :	3750.00	1230
TOTAL (PARTS & LABOUR):		16376.50	

total: 7182.10.

1/s: 5-7K.

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: