



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/ASM22009795/Dvy3-1

AXA INSURANCE PTE LTD

Ref: ~~CS3/ASM22009795/Evy3~~

8 SHENTON WAY #24-01

Date: ~~04/10/2022~~ 10/03/2023

AXA TOWERSINGAPORE 068811

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 7393J	Veh. Inspected	SFT 3619U
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04C3L	Excess (\$)	0.00
Assign From	LOH CYNTHIA HENG XIN YI (SEAH ONG)	Assign Date	04/10/2022 10/03/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/09/2022	Inspection Date	04/10/2022
Survey held at	Messrs Lay Auto Garage Pte Ltd 48 Toh Guan Road East #02-104 Singapore 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--