

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 23.30485 Date: 14th March 2023

Our Ref: CS3/ASM22009795/Dvy3m4-1

M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFT 3619U

INSURED VEHICLE: SHC 7393J ACCIDENT DATE: 30/09/2022

We thank you for your instruction on 10/03/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFT 3619U from MC-COY Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SFT 3619U and SHC 7393J.
- c) Police Report of Vehicles SFT 3619U.
- d) Final Repair Bill of SFT 3619U from M/s Lay Auto Garage Pte Ltd.
- e) Colour damaged vehicle photographs of SFT 3619U.

Pre-Repair Inspection Date: 04/10/2022 at M/s Lay Auto Garage Pte Ltd, 38 Toh Guan Road East #01-56 Enterprise Hub, Singapore 608581.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SFT 3619U

Make & Model : Honda Freed Hybrid 1.5G Auto

Year of Registration : 2019

Chassis Number : GB71084182 Engine Capacity : 1496 cc

- 2. We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.