

ASS. REC. BY:

REF:

MG / 23002562/Ky

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCU 1618J

Yr Regn:

12, 17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Harrier

c.c

1998

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

130647

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTEBB34110J000917

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

d

mm

Rear

R/Bal.

d

mm

L/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

8/13/23

D.O.I.

28/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/3 / 1 Pm @ 1800 Cnhr

Date/Time, File Pass to?



Prel. Report



Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Not withered
11pm @ 1800h
Penny After Rain
3 day.

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 08/03/2023
TP Veh Reg No: SJY4470A

Estimate No: ES2300337/AMK
Date: 28 Mar 2023
Policy No: 8-V0024282-MVA-R003
Veh Reg No: SLU1618J
Make/Model: TOYOTA HARRIER M
GRADE
Chassis No: JTEZB3GH10J000917
Engine No: 8ARZ095709
Reg. Date: 05/12/2017

Estimate Repair Cost to Vehicle No :SLU1618J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	904.00	1 PC	904.00	—
2 REAR BUMPER SPONGE	134.30	1 PC	134.30	—
3 REAR BUMPER CLIP	4.90	5 PC	24.50	—
4 REAR BUMPER LOWER SPOILER	466.00	1 PC	466.00	—
5 REAR BUMPER LH INNER PDC SENSOR	481.90	1 PC	481.90	—
6 REAR BUMPER INNER CENTRE PARKING SENSOR OUTER RIM	24.50	1 PC	24.50	—
7 REAR BUMPER LH RETAINER	28.60	1 PC	28.60	X
			2,063.80	
	Less 25%		515.95	1,547.85
Labour				
8 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, PARKING SENSORS,KNOCKING & REPAIR REAR PANEL & REALIGN THE SAME	400	1 LA	400.00	320
9 PUTTY & RESPRAY REAR BUMPER,PARKING SENSORS,REAR PANEL & ALL AFFECTED AREAS	500	1 LA	500.00	400
10 REMOVE & REFIX REVERSE SENSORS,RESET & REALIGN THE SAME	80	1 LA	80.00	50
			980.00	980.00
Total			S\$ 2,527.85	
Add GST @ 8%			202.23	
Total Amount Payable			S\$ 2,730.08	

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	230C

Vehicle Details

Vehicle No.:	SLU1618J
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER M GRADE
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	8ARZ095709
Chassis No.:	JTEZB3GH10J000917
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$30,808.00
Original Registration Date:	05 Dec 2017
First Registration Date:	05 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$35,132.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Dec 2027
PARF Rebate Amount:	\$24,592.00

Intended COE Rebate Details

COE Expiry Date:	04 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$23,205.00
Total Rebate Amount:	\$47,797.00

The information contained herein is correct as at 09 Mar 2023

OK