

KFS Motor

EQ INSURANCE

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

VEHICLE NO. : SLP429X

ACCIDENT DATE : 09-03-2023 08:30

THIRD PARTY REF. : GBC2352G

INVOICE NO : TEST

DATE : 08-04-2023

ATTN: EQ INSURANCE

INVOICE COST OF REPAIRS TO VEHICLE SLP429X NISSAN QASHQAI

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT HEADLAMP LH	400.00
1	FRONT BUMPER	400.00
1	FRONT BUMPER SIDE RETAINER LH	25.00
10	FRONT BUMPER CLIP@\$2.50	25.00
1	FRONT FENDER LH	420.00
10	FRONT FENDER SHIELD CLIP @\$2.50	25.00
1	FRONT FENDER WHEEL ARCH GARNISH LH	260.00
		1,555.00
	ADD 10 %	
		155.50
	TOTAL (A)	
		1,710.50

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	300.00
1	SPRAY[AINTING CHARGES	400.00

TOTAL (D)		730.00
TOTAL REPAIR COST :		2,440.50
G S T % :		195.24
INVOICE AMOUNT :		
		2,635.74

DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Mar 2023)
Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SLP429X/11/03/2023 13:32
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP LH	0.00	0.00	wt ✓ *480.00 F 400
2	1		*FRONT BUMPER	0.00	0.00	de ✓ *400.00 F —
3	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	? *25.00 F —
4	10		*FRONT BUMPER CLIP	0.00	0.00	ng ✓ *25.00 F —
5	1		*FRONT FENDER LH	0.00	0.00	bl ✓ *420.00 F —
6	1		*FRONT FENDER SHIELD LH	0.00	0.00	x *90.00 F —
7	1		*FRONT FENDER SHIELD CLIP	0.00	0.00	x ✓ *25.00 F —
8	1		*FRONT FENDER WHEEL ARCH GARNISH LH	0.00	0.00	wt ✓ *250.00 F 260
Sub Total (S\$)						1,715.00
+ Margin on L,N Items 10.00% (S\$)						171.50
Total Parts (S\$)						1,886.50

Kan Fook Sing Motor Workshop/SLP429X/11/03/2023 13:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
No new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	400 550.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	30 50.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	300 520.00
Gross Labour Cost (\$\$)			1,120.00

Kan Fook Sing Motor Workshop/SLP429X/11/03/2023 13:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jia 97495747

'WP' 14/3/23 @ 1215pm

7/P Resing before paint.

3 days

Tan Jia @ 11/03/2023

Adrian L

Resing before Paint

SL/S 05/04/23