



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI23002579/Kqy3m4 Date: 24/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	GY 9131G	Veh. Inspected	SKE 5846L	
Policy No.	DMCVSNW00021182204	Coverage (\$)	0.00	
Claim No.	SNM22D205374/C02	Excess (\$)	0.00	
Assign From	LYNN KHONG	Assign Date	10/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS C (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JTDKD3B3401003502	Colour	METALLIC SILVER	
Odometer	202863 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	KAPSEN	9 mm	
L/H Front Tyre	185/60 R15	KAPSEN	9 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	8 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	29/07/2022	Inspection Date	13/03/2023	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	