

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	LIBERTY INSURAI	NCE PTE LTD	Ref:	CS/LIP23002582/Kqy3e2
	51 CLUB STREET, LIBERTY HOUSES	,#03-00 SINGAPORE 069428	Date:	03/04/2023
			Code:	LIP
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SKR 1233M	Veh. Inspected	SFJ 6536H
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/0844	Excess (\$)	0.00
	Assign From	TED SEAH	Assign Date	13/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CITY (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	MRHGM26509P020133	Colour	METALLIC GREY
	Odometer	115308 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/65 R15	YOKOHAMA	9 mm
	L/H Front Tyre	175/65 R15	YOKOHAMA	9 mm
	R/H Rear Tyre	175/65 R15	YOKOHAMA	9 mm
	L/H Rear Tyre	175/65 R15	YOKOHAMA	9 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	08/03/2023	Inspection Date	13/03/2023
	Survey held at	FALCON-AIR AUTO SERVICES	PTE LTD (HQ)	
		176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721		
5a.	Remarks			
	A)REGISTRATION DATE: 13 MAR 2009 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	6 Work	ring Days