



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LIBERTY INSURANCE PTE LTD

51 CLUB STREET, #03-00

LIBERTY HOUSESINGAPORE 069428

Ref: CS/LIP23002583/Uvy3

Date: 13/03/2023

Code: LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 3775C	Veh. Inspected	GBG 1548U
Policy No.		Coverage (\$)	0.00
Claim No.	IVS23/0455	Excess (\$)	0.00
Assign From	TED SEAH	Assign Date	13/03/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/02/2023	Inspection Date	13/03/2023
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--