

Our Ref: YP7132B230307

Date: 26/03/2023

Your Ref:

Allianz Insurance Singapore Pte Ltd  
79 Robison Road #09-01  
Singapore 068897  
Motor Claims Department

Dear Sir

**Traffic Accident Along** 55 Airport Boulevard  
**Involving** YP7132B **and** XE2427D **On** 07/03/2023

We/I, **Goldbell Leasing Pte Ltd** (NRIC / ROC No: 199001196N ), the registered owners of m/vehicle - YP7132B at all material times of the above accident. Our/my vehicle was surveyed by “Allianz” authorized appraiser and we/I based our/my claims on his recommendation for S\$ 7,000-00 being the repair for 05 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle XE2427D when the same was involved in the aforesaid accident with our/my m/vehicle - YP7132B.

We/I whereby you are the insurers of m/vehicle XE2427D and the driver/owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle - YP7132B has suffered loss and damage as follows:

Cost of repairs	S\$	<u>7,000-00</u>
LOU for pre-repair notice 02 days @ S\$ <u>120-00</u> [ 2998 cc Fridge Box Truck]		<u>240-00</u>
LOU Fee for <u>05</u> days @S\$ <u>120-00</u> [ 2998 cc Fridge Box Truck]		<u>600-00</u>
Rental Fee Invoice No: _____		_____
GIA / LTA search fee		<u>2-00</u>
Towing Fee (Cash Sale No _____ )		_____
Survey Fee		_____
<b>Total Amount</b>	<b>S\$</b>	<u>7,842-00</u>

We/I enclose herewith copies of the supporting documents for vehicle no. YP7132B as follows:-

- (i) Motor Accident Report & Documents;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our/my claims as soon as possible.

Please remit us/me your settlement sum in favor of M/s Liu's Brother Auto Engineering Workshop. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,

f-----  


The owner of m/vehicle YP7132B  
Messers **Goldbell Leasing Pte Ltd**  
cc. Liu's Bro Auto Engineering Workshop

**Liu's Brother Auto Engineering Workshop**

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

**ESTIMATE**

Name: Allianz Insurance Company of Singapore Pte Ltd

Address Motor Claims Department

12 Marina View #14-01

Asia Square Tower 2 Singapore 018961

Ref Date:

26/03/2023

Ref No:

YP7132B230307

Vehicle No:

YP7132B

Model / Make:

Mitsubishi Canter

Capacity: 2998 cc

FEB21ER4SDEB (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	<b>Front</b>	Panel	\$ 2,494.90	1	\$ 2,494.90		\$ -
2		Panel "FUSO" Emblem	\$ 163.80	1	\$ 163.80		\$ -
3		Wiper Panel	\$ 1,518.70	1	\$ 1,518.70		\$ -
4		Bumper	\$ 1,929.80	1	\$ 1,929.80		\$ -
5		Bumper Clips 1 set	\$ 50.00	1	\$ 50.00	SN	\$ -
6		Grille	\$ 1,123.40	1	\$ 1,123.40		\$ -
7		Grille Clips 1 set	\$ 50.00	1	\$ 50.00	SN	\$ -
8		"Canter" Emblem	\$ 86.00	1	\$ 86.00		\$ -
9		"Mitsubishi Logo" Motif	\$ 187.00	1	\$ 187.00	N	\$ -
10		Number Plate	\$ 28.00	1	\$ 28.00	SN	\$ -
11	<b>Front Lh</b>	Bumper Side	\$ 441.70	1	\$ 441.70		\$ -
12		Bumper Side Clips 1 set	\$ 45.00	1	\$ 45.00	SN	\$ -
13		Bumper Bracket	\$ 296.30	1	\$ 296.30		\$ -
14		Head Lamp	\$ 1,712.80	1	\$ 1,712.80		\$ -
15		Head Lamp Clips 01 Set	\$ 30.00	1	\$ 30.00	SN	\$ -
16		Signal Lamp	\$ 324.30	1	\$ 324.30		\$ -
17		Signal Lamp Clips 01 Set	\$ 20.00	1	\$ 20.00	SN	\$ -
18		Corner Panel	\$ 486.90	1	\$ 486.90		\$ -
19		Corner Panel Clips 1 set	\$ 28.00	1	\$ 28.00	SN	\$ -
20		Aircon Cooling Coil Unit	\$ 1,950.00	1	\$ 1,950.00		\$ -
21		Mirror Arm	\$ 545.20	1	\$ 545.20		\$ -
22		Side Mirror "Round"	\$ 110.50	1	\$ 110.50		\$ -
23		Side Mirror "Square"	\$ 110.50	1	\$ 110.50		\$ -
24		To check all wiring & electrical component for proper function			\$ 300.00		\$ -
25		Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc ...			\$ 300.00		\$ -
26		To remove & refix air con, re-fill air con gas & test for leakages			\$ 300.00		\$ -
27		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 800.00		\$ -
28		To putty & spray painting & including touch up paint on accident affected areas			\$ 900.00		\$ -
29		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 100.00		\$ -

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 16,432.80

Total amount in Lumpsum Basis for repaired vehicle

\$ 7,000.00

SDL Seven Thousand Only

Liu's Bro Auto Engrg Wks


## INSURER ENQUIRY

Find  
insurer

Vehicle reg. no.

XE2427D

Date of Accident

07/03/2023 

Reset

## % RESULT &amp; RECEIPT

## TP Insurer Enquiry

Insurance ..... Allianz Insurance Singapore P...

Period of Insurance ..... 14/11/2022 - 13/11/2023

Requested By ..... Susan Low (Liu's Brother Auto...

Requested Date ..... 11/03/2023 10:01

## Payment details

Request Amount: **\$S1.85**GST Amount: **\$S0.15**Total Amount Due (GST Inclusive): **\$S2**

## General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

OK