Immediate Advice

To: HSBC LIFE (SINGAPORE) PTE LTD DATE: 6/6/2023

Survey details

Date of loss	3/3/2023
Date of appointment	13/3/2023
Date of survey	28/4/2023
Location of survey	TECH CHOON AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	GBL 8498H
Make and Model	TOYOTA HIACE DX
Date of registration	9/6/2017
Excess	
Market Value	\$42,000.00
Parf Rebate	\$15,579.00
Nett Loss	\$26,421.00

Repair details

Initial Estimate	\$27.293.60
mittai Loumate	Φ2 1,2 2 3.00

Proposed/Revised repair cost:

Parts	\$8,601.75
"Check items (Estimated)	
Labour	\$2,880.00
Total	\$11,481.75
Lump Sum (Estimated)	\$9,150.00

Number of days of repair 7 days (est)

Remarks:

Damages Consistent

The vehicle sustained damages at the front and rear portion

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .