

AUTOLUTION

CARTIMES

CarTimes Autolution Pte Ltd
 160 Sin Ming Drive AutoCity
 #02-04 Singapore 575722
 Tel: 6471 5111
 Email: claims@cartimes.com.sg

VEHICLE NO: SMR5635L

MODEL: MERCS A200

CHASSIS NO: WDD1771872J119915

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER 1525	CM \$ 1,750.00 ✓
FRONT BUMPER RETAINER RHS	CM \$ 110.00 ✓
FOG LAMP GARNISH RHS	my \$ 180.00 ✓
HEADLAMP RHS 3154	R \$ 3,950.00 ✓
HEADLAMP BRACKET RHS Support	CM \$ 780.00 ✓
FRONT FENDER	R \$ 750.00 ✓
FRONT FENDER INNER SHIELD RHS 228	CM \$ 450.00 ✓
FRONT RIM RHS 1580	RM \$ 1,950.00 ✓
FRONT BONNET	R \$ 1,700.00 X
FRONT SENSOR RHS	Shw \$ 240.00 ✓
	\$ 11,860.00
	10% \$ 1,186.00
	\$ 10,674.00
<u>SPECIAL NETT ITEMS</u>	
FRONT BUMPER CLIPS 1 SET	\$ 60.00 ✓
Total	\$ 60.00
TOTAL PARTS	\$ 10,734.00

Not Authorized
Penalty 10 days
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00
4	To provide anti-rust treatment on affected areas	\$ 100.00
5	Dignostic Check	\$ 100.00
6	Transfer tailgate parts	\$ 150.00
7	Alignment Check	\$ 100.00
	Labour Total :	\$ 3,650.00
	TOTAL (PARTS & LABOUR):	\$ 14,384.00

VEHICLE NO: SMR5635L
CHASSIS NO: WDD1771872J119915

[illegible]

<u>LABOUR</u>		
	TOTAL:	\$ -
(LABOUR + PARTS) TOTAL:		\$ 909.00