

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR23002610/y3	
	60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Date:	13/03/2023	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHB 5025R	Veh. Inspected	<u> </u>	SLH 93Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/03/23/2028/MA	Excess (\$)		0.00	
	Assign From	ASHLENE	Assign Date		13/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN Year of Reg.				
	Chassis No.		Colour			
	Odometer -		Steering			
	Brakes	rakes Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.		General Information				
	Accident Date	07/03/2023	Inspection Date			
	Survey held at	PROMPT AUTO SOLUTIONS PT				
		8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					